

## **RF Declaration Letter**

## 2019-04-03

To:

FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

**Product Name**: Elevator IOT Machine

**Model Name**: SOTL5-b

**Series Model Name**: xSOTL5x (x - Where x may be any combination of alphanumeric characters or "-"or

blank.)

FCC ID: 2AR8LSOTL5B

We hereby declare that firmware was set in SOTL5-b had disable Wi-Fi 802.11 n HT40 (2.4G) and 802.11 an+ac (5GHz) support upon system boot-up for all SOTL5-b and xSOTL5x (x - Where x may be any combination of alphanumeric characters or "-"or blank.) system shipment. Consequently, users are NOT accessible to Wi-Fi 802.11 n HT40 (2.4G) and 802.11 an+ac (5GHz).

Datahoist, Inc. assumes the liability against any problems or damages that might occur in relation to this issue.

Sincerely Yours,

Dan Bryant/CEO

dbryant@datahoist.com

8920 Business Park Drive #250, AUSTIN, TX 78759 USA