



## Setup Photos


Revision	Report Date	Reason for Revision
∅	July 5, 2021	Initial Issue.
1	October 9, 2021	TCB Review Updates.




**Radiated Spurious Emissions, 1GHz – 18GHz, Test Setup**




**Substitution Method, Test Setup**



**EIRP Measurement Test Setup View 1**



EIRP Measurement Test Setup View 2



**FCC Part 15B, 30MHz – 1GHz, Test Setup**