



5MHz_High_QPSK_1@24




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 21.JUN.2024 23:09:14

5MHz_High_QPSK_25@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 21.JUN.2024 23:06:45

5MHz_High_16QAM_1@24




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 21.JUN.2024 23:13:51

5MHz_High_16QAM_25@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 21.JUN.2024 23:11:33

10MHz_Low_QPSK_1@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:22:09

10MHz_Low_QPSK_50@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:21:35

10MHz_Low_16QAM_1@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:23:17

10MHz_Low_16QAM_50@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:22:43

10MHz_High_QPSK_1@49




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 21.JUN.2024 23:26:10

10MHz_High_QPSK_50@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 21.JUN.2024 23:25:13

10MHz_High_16QAM_1@49




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 21.JUN.2024 23:27:33

10MHz_High_16QAM_50@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 21.JUN.2024 23:26:51

15MHz_Low_QPSK_1@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:29:03

15MHz_Low_QPSK_75@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:28:29

15MHz_Low_16QAM_1@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:30:13

15MHz_Low_16QAM_75@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:29:38

15MHz_High_QPSK_1@74




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:42:47

15MHz_High_QPSK_75@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:41:53

15MHz_High_16QAM_1@74




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:44:14

15MHz_High_16QAM_75@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:43:31

20MHz_Low_QPSK_1@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:46:25

20MHz_Low_QPSK_100@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:45:49

20MHz_Low_16QAM_1@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:47:38

20MHz_Low_16QAM_100@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:47:01


20MHz_High_QPSK_1@99




20MHz_High_QPSK_100@0



20MHz_High_16QAM_1@99




20MHz_High_16QAM_100@0




B41_3, Normal


3_5MHz_Low_QPSK_1@0



3_5MHz_Low_QPSK_25@0




3_5MHz_Low_16QAM_1@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:54:39

3_5MHz_Low_16QAM_25@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:54:03

3_5MHz_High_QPSK_1@24




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:56:26

3_5MHz_High_QPSK_25@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:55:50

3_5MHz_High_16QAM_1@24




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:57:36

3_5MHz_High_16QAM_25@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 00:57:01

3_10MHz_Low_QPSK_1@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 00:59:18

3_10MHz_Low_QPSK_50@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 00:58:40

3_10MHz_Low_16QAM_1@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 01:00:33

3_10MHz_Low_16QAM_50@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 00:59:56

3_10MHz_High_QPSK_1@49




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 01:02:15

3_10MHz_High_QPSK_50@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 01:01:37


3_10MHz_High_16QAM_1@49




3_10MHz_High_16QAM_50@0




3_15MHz_Low_QPSK_1@0




3_15MHz_Low_QPSK_75@0




3_15MHz_Low_16QAM_1@0



3_15MHz_Low_16QAM_75@0




3_15MHz_High_QPSK_1@74




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 01:10:06

3_15MHz_High_QPSK_75@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 01:09:29

3_15MHz_High_16QAM_1@74




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 01:11:20

3_15MHz_High_16QAM_75@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 01:10:43

3_20MHz_Low_QPSK_1@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 01:13:12

3_20MHz_Low_QPSK_100@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 22.JUN.2024 01:12:33

3_20MHz_Low_16QAM_1@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 01:14:31

3_20MHz_Low_16QAM_100@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 01:13:52

3_20MHz_High_QPSK_1@99




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 01:17:02

3_20MHz_High_QPSK_100@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 01:16:22

3_20MHz_High_16QAM_1@99



ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 01:18:20

3_20MHz_High_16QAM_100@0




ProjectNo.:2402U40702E-RF Tester:Karl Liang
 Date: 22.JUN.2024 01:17:41

Spurious Emissions at Antenna Terminal

FCC Part 22H


B5, Normal

1.4MHz_Low_QPSK_1@0 -25.91dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:26:15

1.4MHz_Low_QPSK_6@0 -25.65dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:26:33

1.4MHz_Middle_QPSK_1@0 -25.68dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:26:50

1.4MHz_Middle_QPSK_6@0 -25.30dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:27:08

1.4MHz_High_QPSK_1@0 -25.55dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:27:26

1.4MHz_High_QPSK_6@0 -25.26dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:27:44

3MHz_Low_QPSK_1@0 -25.57dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:28:32

3MHz_Low_QPSK_15@0 -26.10dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:28:51

3MHz_Middle_QPSK_1@0 -25.33dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:29:10

3MHz_Middle_QPSK_15@0 -25.44dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:29:29

3MHz_High_QPSK_1@0 -25.21dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:29:50

3MHz_High_QPSK_15@0 -26.07dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:31:02

5MHz_Low_QPSK_1@0 -25.43dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:31:58

5MHz_Low_QPSK_25@0 -25.75dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:32:15

5MHz_Middle_QPSK_1@0 -25.84dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:32:33

5MHz_Middle_QPSK_25@0 -25.53dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:32:50

5MHz_High_QPSK_1@0 -25.63dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:33:08

5MHz_High_QPSK_25@0 -24.64dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:33:25

10MHz_Low_QPSK_1@0 -25.19dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:34:11

10MHz_Low_QPSK_50@0 -26.10dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:34:30

10MHz_Middle_QPSK_1@0 -25.43dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:34:49

10MHz_Middle_QPSK_50@0 -26.39dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:35:07

10MHz_High_QPSK_1@0 -25.57dBm



ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:35:26

10MHz_High_QPSK_50@0 -25.40dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 20.JUL.2024 19:35:44

FCC Part 27


Bband , Normal

3_5MHz_Low_QPSK_1@0 -34.30dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:02:24

10MHz_High_QPSK_1@0 -34.22dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:53:49

10MHz_High_QPSK_50@0 -34.86dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:54:09

15MHz_Low_QPSK_1@0 -34.71dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:57:09

15MHz_Low_QPSK_75@0 -34.60dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:57:29

15MHz_Middle_QPSK_1@0 -34.71dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:57:50

15MHz_Middle_QPSK_75@0 -34.16dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:58:11

15MHz_High_QPSK_1@0 -34.44dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:58:38

15MHz_High_QPSK_75@0 -34.96dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:58:59

20MHz_Low_QPSK_1@0 -34.31dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:00:03

20MHz_Low_QPSK_100@0 -34.38dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:00:23

20MHz_Middle_QPSK_1@0 -35.15dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 17:00:44

20MHz_Middle_QPSK_100@0 -34.50dBm




20MHz_High_QPSK_1@0 -34.24dBm




B7 , Normal


20MHz_High_QPSK_100@0 -33.58dBm




5MHz_Low_QPSK_1@0 -34.90dBm




5MHz_Low_QPSK_25@0 -34.45dBm



5MHz_Middle_QPSK_1@0 -34.26dBm




5MHz_Middle_QPSK_25@0 -34.21dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:40:46

5MHz_High_QPSK_1@0 -34.55dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:41:05

5MHz_High_QPSK_25@0 -34.37dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:41:25

10MHz_Low_QPSK_1@0 -33.92dBm




ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:42:13

10MHz_Low_QPSK_50@0 -35.17dBm



ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:42:33

10MHz_Middle_QPSK_1@0 -34.68dBm



ProjectNo.:2402U40702E-RF Tester:Karl Liang
Date: 23.JUL.2024 16:42:52