



Please refer to following plots:

Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:17:33

Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:18:03

Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:18:29

Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:18:59

Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:19:31


Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:20:01




Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:21:01

Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:21:30

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:22:03

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:22:26

Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:22:55


Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:23:22




Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:24:30

Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:24:53

Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:25:23


Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:25:46




Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:26:21

Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:26:45

Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:27:45

Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:28:08

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:28:38


Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:29:01




Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:29:24

Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:29:50

Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:31:13

Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:31:44

Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:32:13


Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:32:44




Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:33:14

Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:33:40

Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:34:48

Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:35:21

Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:35:54


Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:36:17




Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:36:50

Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:37:20

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:37:52

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:38:12

Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:38:47


Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:39:17




Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:39:52

Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:40:16

Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:41:10

Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:41:39

Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:42:09


Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:42:39




Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:43:15

Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:43:35

Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:44:39

Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:45:09

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:45:39


Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:46:02




Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:46:35

Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:46:58

Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:47:52

Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:48:12

Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:48:42


Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:49:02




Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:49:32

Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:49:56

Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:50:50

Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:51:13

Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:51:46


Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:52:13




Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:52:43

Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:53:13

Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:54:04

Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:54:28

Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:54:55


Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 16.SEP.2022 18:55:22




Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:55:52

Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 16.SEP.2022 18:56:12

Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:57:11

Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 16.SEP.2022 18:57:41

Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 18:58:11


Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)



Date: 16.SEP.2022 18:58:41




Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 18:59:10

Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 16.SEP.2022 18:59:30

Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 19:00:27

Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 16.SEP.2022 19:00:58

Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 19:01:30


Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 16.SEP.2022 19:01:51




Band 5\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 19:02:17

Band 5\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 16.SEP.2022 19:02:54

Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 19:03:47

Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.SEP.2022 19:04:20

Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 19:04:53


Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)



Date: 16.SEP.2022 19:05:20




Band 5\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 19:05:52

Band 5\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 16.SEP.2022 19:06:19

Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 19:07:16

Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.SEP.2022 19:07:43

Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 16.SEP.2022 19:08:20


Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 16.SEP.2022 19:08:50




Band 5\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 16.SEP.2022 19:09:26

Band 5\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 16.SEP.2022 19:09:46

Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 11:40:35

Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:41:12

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 11:41:54


Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)



Date: 17.SEP.2022 11:42:20




Band 7\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 11:42:49

Band 7\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:43:22

Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 11:44:17

Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:44:47

Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 11:45:19


Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)



Date: 17.SEP.2022 11:45:39




Band 7\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 11:46:11

Band 7\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:46:45

Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 11:47:47

Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:48:10

Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 11:48:43


Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)



Date: 17.SEP.2022 11:49:06




Band 7\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 11:49:35

Band 7\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:49:59

Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 11:51:01

Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:51:31

Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 11:52:04


Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 17.SEP.2022 11:52:30




Band 7\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 11:53:03

Band 7\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 17.SEP.2022 11:53:29

Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:06:52

Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 17.SEP.2022 12:07:15

Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 17-SEP-2022 12:07:41


Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)



Date: 17-SEP-2022 12:08:04




Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:08:37

Band 12\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 17.SEP.2022 12:09:00

Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:10:00

Band 12\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 17.SEP.2022 12:10:30

Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 12:11:01


Band 12\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 17.SEP.2022 12:11:25




Band 12\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:11:47

Band 12\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 17.SEP.2022 12:12:17

Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:13:08

Band 12\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 17.SEP.2022 12:13:37

Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Band 12\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)






Band 12\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:14:59

Band 12\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 17.SEP.2022 12:15:25

Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:16:13

Band 12\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 17.SEP.2022 12:16:42

Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 12:17:11


Band 12\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 17.SEP.2022 12:17:41




Band 12\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:18:11

Band 12\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 17.SEP.2022 12:18:37

Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:19:12

Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:19:35

Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 12:20:03


Band 66\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)



Date: 17.SEP.2022 12:20:23




Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:20:59

Band 66\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:21:25

Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:22:22

Band 66\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:22:45

Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 12:23:17


Band 66\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 17.SEP.2022 12:23:44




Band 66\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:24:13

Band 66\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:24:43

Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:26:02

Band 66\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:26:26

Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 12:27:02


Band 66\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 17.SEP.2022 12:27:28




Band 66\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:28:01

Band 66\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:28:27

Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:29:21

Band 66\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:29:54

Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 12:30:23


Band 66\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)



Date: 17.SEP.2022 12:30:50




Band 66\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:31:25

Band 66\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:31:46

Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:32:43

Band 66\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:33:09

Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 12:33:42


Band 66\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 17.SEP.2022 12:34:05




Band 66\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:34:35

Band 66\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:35:01

Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:36:52

Band 66\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:37:15

Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 12:37:45


Band 66\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 17.SEP.2022 12:38:15




Band 66\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 12:38:42

Band 66\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.SEP.2022 12:39:05

Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 18:44:30

Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 17.SEP.2022 18:44:50

Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 18:45:23


Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)



Date: 17.SEP.2022 18:45:48




Band 17\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 18:46:17

Band 17\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 17.SEP.2022 18:46:45

Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.SEP.2022 18:47:44

Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 17.SEP.2022 18:48:12

Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 18:48:43


Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 17.SEP.2022 18:49:16




Band 17\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 17.SEP.2022 18:49:50

Band 17\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 17.SEP.2022 18:50:10