



Please refer to following plots:




Date: 1.NOV.2022 09:11:24




Date: 1.NOV.2022 09:11:30

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 1.NOV.2022 09:11:37

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 1.NOV.2022 09:11:44

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 1.NOV.2022 09:12:36

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 1.NOV.2022 09:12:42

Band 2_3 MHz_High_QPSK_RB15#0




Date: 1.NOV.2022 09:12:49

Band 2_3 MHz_High_16QAM_RB15#0




Date: 1.NOV.2022 09:12:56

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 1.NOV.2022 09:13:48

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 1.NOV.2022 09:13:55

Band 2_5 MHz_High_QPSK_RB25#0




Date: 1.NOV.2022 09:14:02

Band 2_5 MHz_High_16QAM_RB25#0




Date: 1.NOV.2022 09:14:10

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 1.NOV.2022 09:15:50

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 1.NOV.2022 09:15:57

Band 2_10 MHz_High_QPSK_RB50#0




Date: 1.NOV.2022 09:16:06

Band 2_10 MHz_High_16QAM_RB50#0




Date: 1.NOV.2022 09:16:13

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 1.NOV.2022 09:17:22

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 1.NOV.2022 09:17:28

Band 2_15 MHz_High_QPSK_RB75#0




Date: 1.NOV.2022 09:17:36

Band 2_15 MHz_High_16QAM_RB75#0




Date: 1.NOV.2022 09:17:42

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 1.NOV.2022 09:18:51

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 1.NOV.2022 09:18:58

Band 2_20 MHz_High_QPSK_RB100#0




Date: 1.NOV.2022 09:19:05

Band 2_20 MHz_High_16QAM_RB100#0




Date: 1.NOV.2022 09:19:12

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 1.NOV.2022 09:19:22

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 1.NOV.2022 09:19:29

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 1.NOV.2022 09:19:35

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 1.NOV.2022 09:19:41

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 1.NOV.2022 09:20:28

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 1.NOV.2022 09:20:35

Band 4_3 MHz_High_QPSK_RB15#0




Date: 1.NOV.2022 09:20:41

Band 4_3 MHz_High_16QAM_RB15#0




Date: 1.NOV.2022 09:20:47

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 1.NOV.2022 09:21:19

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 1.NOV.2022 09:21:26

Band 4_5 MHz_High_QPSK_RB25#0




Date: 1.NOV.2022 09:21:34

Band 4_5 MHz_High_16QAM_RB25#0




Date: 1.NOV.2022 09:21:40

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 1.NOV.2022 09:22:25

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 1.NOV.2022 09:22:33

Band 4_10 MHz_High_QPSK_RB50#0




Date: 1.NOV.2022 09:22:41

Band 4_10 MHz_High_16QAM_RB50#0




Date: 1.NOV.2022 09:22:48

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 1.NOV.2022 09:23:20

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 1.NOV.2022 09:23:26

Band 4_15 MHz_High_QPSK_RB75#0




Date: 1.NOV.2022 09:23:34

Band 4_15 MHz_High_16QAM_RB75#0




Date: 1.NOV.2022 09:23:40

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 1.NOV.2022 09:24:12

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 1.NOV.2022 09:24:19

Band 4_20 MHz_High_QPSK_RB100#0




Date: 1.NOV.2022 09:24:26

Band 4_20 MHz_High_16QAM_RB100#0




Date: 1.NOV.2022 09:24:33

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 1.NOV.2022 09:24:42

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 1.NOV.2022 09:24:48

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 1.NOV.2022 09:24:54

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 1.NOV.2022 09:25:00

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 1.NOV.2022 09:25:46

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 1.NOV.2022 09:25:52

Band 5_3 MHz_High_QPSK_RB15#0




Date: 1.NOV.2022 09:25:59

Band 5_3 MHz_High_16QAM_RB15#0




Date: 1.NOV.2022 09:26:05

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 1.NOV.2022 09:26:52

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 1.NOV.2022 09:26:58

Band 5_5 MHz_High_QPSK_RB25#0




Date: 1.NOV.2022 09:27:05

Band 5_5 MHz_High_16QAM_RB25#0




Date: 1.NOV.2022 09:27:11

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 1.NOV.2022 09:28:07

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 1.NOV.2022 09:28:14

Band 5_10 MHz_High_QPSK_RB50#0




Date: 1.NOV.2022 09:28:22

Band 5_10 MHz_High_16QAM_RB50#0




Date: 1.NOV.2022 09:28:30

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 1.NOV.2022 09:33:11

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 1.NOV.2022 09:33:17

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 1.NOV.2022 09:33:24

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 1.NOV.2022 09:33:30

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 1.NOV.2022 09:34:21

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 1.NOV.2022 09:34:28

Band 12_3 MHz_High_QPSK_RB15#0




Date: 1.NOV.2022 09:34:34

Band 12_3 MHz_High_16QAM_RB15#0




Date: 1.NOV.2022 09:34:40

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 1.NOV.2022 09:35:27

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 1.NOV.2022 09:35:35

Band 12_5 MHz_High_QPSK_RB25#0




Date: 1.NOV.2022 09:35:41

Band 12_5 MHz_High_16QAM_RB25#0




Date: 1.NOV.2022 09:35:47

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 1.NOV.2022 09:36:21

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 1.NOV.2022 09:36:29

Band 12_10 MHz_High_QPSK_RB50#0




Date: 1.NOV.2022 09:36:36

Band 12_10 MHz_High_16QAM_RB50#0




Date: 1.NOV.2022 09:36:43

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 1.NOV.2022 09:36:53

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 1.NOV.2022 09:37:00

Band 17_5 MHz_High_QPSK_RB25#0




Date: 1.NOV.2022 09:37:07

Band 17_5 MHz_High_16QAM_RB25#0




Date: 1.NOV.2022 09:37:13

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 1.NOV.2022 09:37:46

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 1.NOV.2022 09:37:54

Band 17_10 MHz_High_QPSK_RB50#0




Date: 1.NOV.2022 09:38:01

Band 17_10 MHz_High_16QAM_RB50#0




Date: 1.NOV.2022 09:38:08

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 1.NOV.2022 09:38:18

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 1.NOV.2022 09:38:24

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 1.NOV.2022 09:38:31

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 1.NOV.2022 09:38:37

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 1.NOV.2022 09:39:09

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 1.NOV.2022 09:39:15

Band 66_3 MHz_High_QPSK_RB15#0




Date: 1.NOV.2022 09:39:22

Band 66_3 MHz_High_16QAM_RB15#0




Date: 1.NOV.2022 09:39:28

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 1.NOV.2022 09:40:01

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 1.NOV.2022 09:40:07

Band 66_5 MHz_High_QPSK_RB25#0




Date: 1.NOV.2022 09:40:15

Band 66_5 MHz_High_16QAM_RB25#0




Date: 1.NOV.2022 09:40:23

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 1.NOV.2022 09:40:55

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 1.NOV.2022 09:41:03

Band 66_10 MHz_High_QPSK_RB50#0




Date: 1.NOV.2022 09:41:11

Band 66_10 MHz_High_16QAM_RB50#0




Date: 1.NOV.2022 09:41:19

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 1.NOV.2022 09:41:51

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 1.NOV.2022 09:41:58

Band 66_15 MHz_High_QPSK_RB75#0




Date: 1.NOV.2022 09:42:05

Band 66_15 MHz_High_16QAM_RB75#0




Date: 1.NOV.2022 09:42:12

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 1.NOV.2022 09:42:43

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 1.NOV.2022 09:42:50

Band 66_20 MHz_High_QPSK_RB100#0




Date: 1.NOV.2022 09:42:58

Band 66_20 MHz_High_16QAM_RB100#0




Date: 1.NOV.2022 09:43:04


Band 7_5 MHz_Low_QPSK_RB25#0



Band 7_5 MHz_Low_16QAM_RB25#0




Band 7_5 MHz_High_QPSK_RB25#0




Date: 17.SEP.2022 14:34:13

Band 7_5 MHz_High_16QAM_RB25#0




Date: 17.SEP.2022 14:36:21

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 17.SEP.2022 14:56:42

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 17.SEP.2022 14:57:45

Band 7_10 MHz_High_QPSK_RB50#0




Date: 17.SEP.2022 14:59:15

Band 7_10 MHz_High_16QAM_RB50#0




Date: 17.SEP.2022 15:01:53

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 17.SEP.2022 15:05:32

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 17.SEP.2022 15:04:45

Band 7_15 MHz_High_QPSK_RB75#0




Date: 17.SEP.2022 15:08:06

Band 7_15 MHz_High_16QAM_RB75#0




Date: 17.SEP.2022 15:08:55

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 17.SEP.2022 15:12:22

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 17.SEP.2022 15:13:01

Band 7_20 MHz_High_QPSK_RB100#0



Date: 17.SEP.2022 15:16:10

Band 7_20 MHz_High_16QAM_RB100#0



Date: 17.SEP.2022 15:14:16