




22





23



15




X1



7


26

28



1X3


1X3



26




X4



30



X4



31



32



X2




X2



X1 X1


X2



27



X4




34



X2



X1




36



X1



X2



35




X1



X1





X1




37



28




38




39





40




29




42



43




44






30

46






Jeep


Assembly difficulty




1

2






3





5









4


6




1X5






10







11

13







15




16




17




18



19





21



20


22



1X2







X1


X1




1X2









27





29



28



30



1X3


1X3

39





1X2


31





32



33








40



37

35








39

40

41




42




43

45






43





44

46






47



48




49



50




X2



44




X1 X1



51




X1 X2




52

53




45


54




15 X1 X5




15



55




1X2








57




x1 x2




46






63




64



65




65




66



67





69




68

70




1X2


49




71



x1 x2





73



x6

75



51

Assembly Guide for More Robots

Please find the assembly guide for 15+ more robots in the APP.



Balance



Motorcycle



Rubber Band Racing Tricycle



Delivery Man



Dragon Tiger Chariot



Tricycle




Chariot




Music Box



Telegraph Machine



Drawing Robot



Parking System



Paper Crane Robot



Tiger



Football Robot



Sumo Robot



FAQ

The main control unit cannot be paired with APP?

Please check if the Bluetooth of your device is turned on. If the Bluetooth is off, please turn it on. If the Bluetooth is turned on, please turn off the main control unit, then turn it on, and restart the APP, then try to connect to Bluetooth again.

Please check if the power of main control units is enough. If not, please replace the battery.



Apitor Technology Co., Ltd.
support@apitor.com www.apitor.com