Shenzhen Glory Star Technology Industrial Co., Ltd

Add: Room 2102, Block 1 st, Yi Luan Building, Xixiang Road 230, BaoAn

District, Shenzhen, China

Tel: 0755-26609516 Fax: 0755-26609516

E-mail: sales03@glorystar-tec.com

2022/10/10

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road

Columbia, MD 21046

FCC ID Cover Letter

The <u>Shenzhen Glory Star Technology Industrial Co.</u>, <u>Ltd</u> here by submits justification for placing the FCC ID in the Associated charging case.


According to the FCC Regulation and Guidance (KDB Publication 784748 D01 v09r01) allows for the FCC ID to be moved to the charging case if the device is unquestionably too small for the FCC ID to be printed.

Referring to the above quote, as the device is too small (FCC ID: 2AS7V-TWS046) to be printed. The FCC ID will be moved to the and charging case. The details are as below:


A. Side surface (A): The curvature shape of the silicone sleeve back cover is not flat, so it's hard to affix the label on the surface of the earbuds.

B. Top cover (B): The plastic logo of the top cover does not provide enough physical space to fit the printing of the FCC ID according to below reference picture.





Conclusion: Based on the above description of area A to B, we conclude that the device is unquestionably too small for enabling the FCC certification No. to be printed onto any surface. We therefore request to move the FCC certification No. to the charging case.



Sincerely,

Signature: Ran ?

Printed Name: Vian Yu

Title: Manager