

## **Exhibit: Internal Photos**

Report File #: 7169006356RC-000

© TÜV SÜD Canada Inc. This test report shall not be reproduced except in full, without written approval of TÜV SÜD Canada Inc

| Client      | Innovere Medical Inc                    |        |
|-------------|---|--------|
| Product     | IVID0608                                |        |
| Standard(s) | FCC 15.407 (b) & RSS-247 Clause 6.2.1.2 | Canada |




Figure 1 – EUT Internal Photo Back

| Page 2 of 3 | Report Issued: 11/20/2020 |  | Report File #: 7169006356RC-000 |
|-------------|---------------------------|--|---------------------------------|
|-------------|---------------------------|--|---------------------------------|

| Client      | Innovere Medical Inc                    |        |
|-------------|---|--------|
| Product     | IVID0608                                | SUD    |
| Standard(s) | FCC 15.407 (b) & RSS-247 Clause 6.2.1.2 | Canada |




Figure 2 – EUT Internal Photo Front

Note: Changes are highlighted by red circle.

| Page 3 of 3 | Report Issued: 11/20/2020 | Report File #: 7169006356RC-000 |
|-------------|---------------------------|---------------------------------|
|             |                           |                                 |