

Document ID	https://docs.google.com/document/d/1Y-8yeDedB4FUwR-mji23fJN0CqKMdist/edit
Responsible	Oystein Moldsvor
Classification	Confidential

Revision History Table

Named revision	Date	Comment:
01	2022-07-04	First version shared with TÜV SÜD

Internal Photos




Figure 1: Closeup picture of components inside the shield boxes of part 102545 - SDS Module (US)




Figure 2: Picture of **component side** of part 102545 - SDS Module (US).
The RF shield boxes are removed.
The antenna location is at the top and left side of the PCB marked "ANT 1" and "ANT 2" respectively

