

**Sutro Connect Inc.**  
181 2nd St.#21, San Francisco, CA 94105 United States

**Class II Permissive Change Letter**

FCC ID: **2ATKG-RAD78011**

Date: Oct. 26, 2021

To:  
Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, MD

Subject: Request Class II Permissive Change for FCC ID: **2ATKG-RAD78011**

To Whom It May Concern,

The purpose of this letter is request a Class II Permissive Change for FCC ID: **2ATKG-RAD78011** original grant date: 09/30/2019;

Applicant: **Sutro Connect Inc.**

The main change filed under this application is the main control IC , Antenna and battery were changed, meet KDB 178919 D01: Hardware changes as follows;

Item	Description	Yes / No	Answer from applicant
1	Hardware changes	Yes	1.Some IC change and layout Modify to match new IC. Add IC: MP1461/MP1462/MP8801DJ/ LMV393/TB6612FNG/TMP112AIDRLR; Delete IC:SY8263/XC6214P332PR-G/ DA213B/SGM8199/DH627S/GXTS03/BL24C08F- RRRC/SGM4551YN8G/XC6214P332PR-G /GXTS03 2.Antenna added gold plating 3.Battery change from LG to BAK.
2	There is no increase in the output power rating (unless such exceptions are permitted by rules or KDB publications – see V) G)).	Yes	Original power was 0.0789 W for RoLa, new power is 0.0719 W for RoLa.
3	The Equipment Class remains the same. (Changes that require a new Equipment Class code require a new grant of certification (FCC ID), except for SDR approvals.)	Yes	Same as original application; Equipment Class remains is DTS.
4	RF exposure changes must	Yes	Update revised RF exposure report;

**Sutro Connect Inc.**

181 2nd St.#21, San Francisco, CA 94105 United States

	be addressed		
5	There are no other changes to the device that indicate a need for a new FCC ID.	Yes	No any change.

I attest that such change will affect the RF function out of the grant conditions, just need measured following items as follows;

Maximum Conducted Output Power  
Radiated Spurious Emissions  
Emissions at Restricted Band  
AC Conducted Emissions  
RF Exposure Evaluation

Should you have any questions or comments regarding this matter, please have my best attention.

Sincerely,



(Signed)

Name / Title: Ravi Kurani / President

Company: Sutro Connect Inc.

Address: 181 2nd St.#21, San Francisco, CA 94105 United States

Phone: (951) 907-2532

Fax: /

E-Mail: eng@mysutro.com