

Page 1 of 20

Report No.: STS2007301W12

Conducted Spurious LTE BAND-2









Shenzhen STS Test Services Co., Ltd.






Shenzhen STS Test Services Co., Ltd.










Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.










Shenzhen STS Test Services Co., Ltd.




LTE BAND-4



Shenzhen STS Test Services Co., Ltd.






Shenzhen STS Test Services Co., Ltd.




LTE BAND-4



Shenzhen STS Test Services Co., Ltd.






Shenzhen STS Test Services Co., Ltd.





Shenzhen STS Test Services Co., Ltd.








LTE BAND-5



Shenzhen STS Test Services Co., Ltd.








LTE BAND-7











Shenzhen STS Test Services Co., Ltd.