



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:05:04

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:05:17

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:05:38

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:05:49

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:06:07

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:06:18

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:06:40

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:06:51

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:07:09

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:07:20

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:07:38

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:07:49

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:08:08

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:08:19

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:08:37

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:08:48

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:09:06

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:09:17

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:09:38

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:09:50

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:10:13

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:10:24

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:10:44

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:10:56

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:11:21

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:11:33

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:12:00

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:12:11

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:12:39

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:12:50

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:13:19

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:13:31

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:13:58

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:14:09

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.MAY.2022 14:14:33

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 17.MAY.2022 14:14:45

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.MAY.2022 11:56:15

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 17.MAY.2022 11:56:27

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.MAY.2022 11:56:44

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 17.MAY.2022 11:56:56

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.MAY.2022 11:57:13

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 17.MAY.2022 11:57:25

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.MAY.2022 11:57:43

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.MAY.2022 11:57:58

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.MAY.2022 11:58:15

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.MAY.2022 11:58:27

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.MAY.2022 11:58:44

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.MAY.2022 11:58:56

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 11:59:17

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.MAY.2022 11:59:29

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 11:59:46

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.MAY.2022 11:59:58

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:00:18

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:00:30

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:00:50

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:01:02

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:01:22

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:01:33

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:01:53

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:02:04

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:02:23

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:02:34

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:02:55

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:03:06

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:03:27

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:03:38

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:03:57

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:04:08

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:04:29

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:04:40

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:04:58

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:05:09

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:05:31

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:05:42

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:06:00

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:06:14

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:06:32

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:06:43

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:07:04

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:07:15

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:07:38

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:07:50

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 12:08:09

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 17.MAY.2022 12:08:21

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 20:49:37

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.MAY.2022 20:49:48

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 20:50:06

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.MAY.2022 20:50:17

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.MAY.2022 20:50:38

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.MAY.2022 20:50:50

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 20:51:11

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.MAY.2022 20:51:22

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 20:51:42

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.MAY.2022 20:51:54

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.MAY.2022 20:52:13

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.MAY.2022 20:52:25

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.MAY.2022 20:52:51

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.MAY.2022 20:53:02

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.MAY.2022 20:53:26

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.MAY.2022 20:53:38

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.MAY.2022 20:54:05

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.MAY.2022 20:54:16

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.MAY.2022 20:54:45

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.MAY.2022 20:54:57

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.MAY.2022 20:55:21

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.MAY.2022 20:55:32

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 17.MAY.2022 20:56:00

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 17.MAY.2022 20:56:11