



Appendix B

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:47:16

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 11.JAN.2022 19:02:40

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:47:46

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 11.JAN.2022 19:03:53

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:48:14

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 11.JAN.2022 19:04:41

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:48:42

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 22.DEC.2021 14:48:52

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:49:09

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 11.JAN.2022 19:05:36

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:49:36

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 11.JAN.2022 19:06:17

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:50:04

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 22.DEC.2021 14:50:15

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:50:35

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 22.DEC.2021 14:50:45

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:51:02

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 22.DEC.2021 14:51:12

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:51:32

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 22.DEC.2021 14:51:43

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:52:05

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 22.DEC.2021 14:52:15

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:52:37

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 22.DEC.2021 14:52:48

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:53:12

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 22.DEC.2021 14:53:23

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:54:00

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 22.DEC.2021 14:54:10

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:54:48

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 22.DEC.2021 14:54:59

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:55:24

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 11.JAN.2022 19:07:33

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:56:16

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 11.JAN.2022 19:07:53

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 22.DEC.2021 14:57:08

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 11.JAN.2022 19:08:16

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:39:30

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:39:40

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:39:57

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:40:08

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:40:25

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:40:35

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:40:55

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:41:05

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:41:23

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:41:33

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:41:53

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:42:04

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:42:23

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:42:33

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:42:50

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:43:01

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:43:18

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:43:28

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:43:50

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:44:01

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:44:20

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:44:31

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:44:50

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:45:00

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:45:20

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:45:31

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:45:51

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:46:01

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:46:19

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:46:29

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:46:51

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:47:02

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:47:19

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:47:30

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:47:49

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:48:00

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:48:23

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:48:34

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:48:54

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:49:07

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:49:24

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:49:38

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:50:00

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:50:11

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:50:33

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:50:43

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.JAN.2022 10:51:03

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.JAN.2022 10:51:13

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 23.DEC.2021 09:25:40

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 23.DEC.2021 09:25:50

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 23.DEC.2021 09:26:07

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 23.DEC.2021 09:26:17

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 23.DEC.2021 09:26:34

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 23.DEC.2021 09:26:45

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 23.DEC.2021 09:27:08

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 23.DEC.2021 09:27:19

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 23.DEC.2021 09:27:37

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 23.DEC.2021 09:27:48

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 23.DEC.2021 09:28:07

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 23.DEC.2021 09:28:17

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 23.DEC.2021 09:28:46

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 23.DEC.2021 09:28:57

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 23.DEC.2021 09:29:20

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 23.DEC.2021 09:29:31

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 23.DEC.2021 09:29:57

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 23.DEC.2021 09:30:11

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 23.DEC.2021 09:30:38

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 23.DEC.2021 09:30:49

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 23.DEC.2021 09:31:15

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 23.DEC.2021 09:31:26

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 23.DEC.2021 09:31:49

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 23.DEC.2021 09:32:00