



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 12.NOV.2022 11:39:47

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 12.NOV.2022 11:39:54

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 12.NOV.2022 11:40:02

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 12.NOV.2022 11:40:10

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 12.NOV.2022 11:40:20

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 12.NOV.2022 11:40:28

Band 2_3 MHz_High_QPSK_RB15#0




Date: 12.NOV.2022 11:40:36

Band 2_3 MHz_High_16QAM_RB15#0




Date: 12.NOV.2022 11:40:45

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 12.NOV.2022 11:40:55

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 12.NOV.2022 11:41:03

Band 2_5 MHz_High_QPSK_RB25#0




Date: 12.NOV.2022 11:41:12

Band 2_5 MHz_High_16QAM_RB25#0




Date: 12.NOV.2022 11:41:20

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 12.NOV.2022 11:41:32

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 12.NOV.2022 11:41:41

Band 2_10 MHz_High_QPSK_RB50#0




Date: 12.NOV.2022 11:41:51

Band 2_10 MHz_High_16QAM_RB50#0




Date: 12.NOV.2022 11:42:00

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 12.NOV.2022 11:42:11

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 12.NOV.2022 11:42:19

Band 2_15 MHz_High_QPSK_RB75#0




Date: 12.NOV.2022 11:42:28

Band 2_15 MHz_High_16QAM_RB75#0




Date: 12.NOV.2022 11:42:36

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 12.NOV.2022 11:42:47

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 12.NOV.2022 11:42:55

Band 2_20 MHz_High_QPSK_RB100#0




Date: 12.NOV.2022 11:43:04

Band 2_20 MHz_High_16QAM_RB100#0




Date: 12.NOV.2022 11:43:12

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 12.NOV.2022 13:37:16

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 12.NOV.2022 13:37:23

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 12.NOV.2022 13:37:31

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 12.NOV.2022 13:37:38

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 12.NOV.2022 13:37:48

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 12.NOV.2022 13:37:56

Band 5_3 MHz_High_QPSK_RB15#0




Date: 12.NOV.2022 13:38:04

Band 5_3 MHz_High_16QAM_RB15#0




Date: 12.NOV.2022 13:38:12

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 12.NOV.2022 13:38:23

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 12.NOV.2022 13:38:30

Band 5_5 MHz_High_QPSK_RB25#0




Date: 12.NOV.2022 13:38:39

Band 5_5 MHz_High_16QAM_RB25#0




Date: 12.NOV.2022 13:38:47

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 12.NOV.2022 13:38:59

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 12.NOV.2022 13:39:08

Band 5_10 MHz_High_QPSK_RB50#0




Date: 12.NOV.2022 13:39:18

Band 5_10 MHz_High_16QAM_RB50#0




Date: 12.NOV.2022 13:39:28

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 12.NOV.2022 13:39:41

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 12.NOV.2022 13:39:49

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 12.NOV.2022 13:39:57

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 12.NOV.2022 13:40:04

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 12.NOV.2022 13:40:16

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 12.NOV.2022 13:40:24

Band 12_3 MHz_High_QPSK_RB15#0




Date: 12.NOV.2022 13:40:32

Band 12_3 MHz_High_16QAM_RB15#0




Date: 12.NOV.2022 13:40:39

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 12.NOV.2022 13:40:51

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 12.NOV.2022 13:41:00

Band 12_5 MHz_High_QPSK_RB25#0




Date: 12.NOV.2022 13:41:08

Band 12_5 MHz_High_16QAM_RB25#0




Date: 12.NOV.2022 13:41:16

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 12.NOV.2022 13:41:28

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 12.NOV.2022 13:41:38

Band 12_10 MHz_High_QPSK_RB50#0




Date: 12.NOV.2022 13:41:47

Band 12_10 MHz_High_16QAM_RB50#0




Date: 12.NOV.2022 13:41:55

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 15.NOV.2022 10:44:53

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 15.NOV.2022 10:46:03

Band 7_5 MHz_High_QPSK_RB25#0




Date: 15.NOV.2022 10:46:42

Band 7_5 MHz_High_16QAM_RB25#0




Date: 15.NOV.2022 10:47:00

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 15.NOV.2022 10:51:29

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 15.NOV.2022 10:51:53

Band 7_10 MHz_High_QPSK_RB50#0




Date: 15.NOV.2022 10:52:31

Band 7_10 MHz_High_16QAM_RB50#0




Date: 15.NOV.2022 10:53:07

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 15.NOV.2022 10:53:07

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 15.NOV.2022 10:54:07

Band 7_15 MHz_High_QPSK_RB75#0




Date: 15.NOV.2022 10:54:35

Band 7_15 MHz_High_16QAM_RB75#0




Date: 15.NOV.2022 10:54:59

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 15.NOV.2022 10:55:44

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 15.NOV.2022 10:56:19

Band 7_20 MHz_High_QPSK_RB100#0




Date: 15.NOV.2022 10:57:02

Band 7_20 MHz_High_16QAM_RB100#0




Date: 15.NOV.2022 10:57:26

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 15.NOV.2022 11:06:48

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 15.NOV.2022 11:07:18

Band 41_5 MHz_High_QPSK_RB25#0




Date: 15.NOV.2022 11:08:11

Band 41_5 MHz_High_16QAM_RB25#0




Date: 15.NOV.2022 11:08:33

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 15.NOV.2022 11:09:20

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 15.NOV.2022 11:09:41

Band 41_10 MHz_High_QPSK_RB50#0




Date: 15.NOV.2022 11:10:09

Band 41_10 MHz_High_16QAM_RB50#0




Date: 15.NOV.2022 11:10:29

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 15.NOV.2022 11:10:29

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 15.NOV.2022 11:11:49

Band 41_15 MHz_High_QPSK_RB75#0




Date: 15.NOV.2022 11:12:35

Band 41_15 MHz_High_16QAM_RB75#0




Date: 15.NOV.2022 11:13:03

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 15.NOV.2022 11:14:07

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 15.NOV.2022 11:14:29

Band 41_20 MHz_High_QPSK_RB100#0



Date: 15.NOV.2022 11:15:02

Band 41_20 MHz_High_16QAM_RB100#0



Date: 15.NOV.2022 11:15:47