

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AUF1-FT-05FL
19-0287
November 5, 2019
OKYANUS TEKNOLOJİ
FT-05FL

External Photographs




Figure 1. EUT Top View

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AUF1-FT-05FL
19-0287
November 5, 2019
OKYANUS TEKNOLOJI
FT-05FL



Figure 2. EUT Side View 1

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AUF1-FT-05FL
19-0287
November 5, 2019
OKYANUS TEKNOLOJİ
FT-05FL



Figure 3. EUT Side View 2

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AUF1-FT-05FL
19-0287
November 5, 2019
OKYANUS TEKNOLOJİ
FT-05FL



Figure 4. EUT Side View 3

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AUF1-FT-05FL
19-0287
November 5, 2019
OKYANUS TEKNOLOJI
FT-05FL



Figure 5. EUT Side View 4

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AUF1-FT-05FL
19-0287
November 5, 2019
OKYANUS TEKNOLOJI
FT-05FL



Figure 6. EUT Bottom