

US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15 Certification  
2AUF1-FT-05FL  
19-0287  
November 5, 2019  
OKYANUS TEKNOLOJI  
FT-05FL

## Internal Photographs



Figure 1. Top Cover Removed (Main PCB)

US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:


FCC Part 15 Certification  
2AUF1-FT-05FL  
19-0287  
November 5, 2019  
OKYANUS TEKNOLOJI  
FT-05FL



Figure 2. Main PCB

US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15 Certification  
2AUF1-FT-05FL  
19-0287  
November 5, 2019  
OKYANUS TEKNOLOJI  
FT-05FL



**Figure 3. Main PCB Back Side**

US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15 Certification  
2AUFI-FT-05FL  
19-0287  
November 5, 2019  
OKYANUS TEKNOLOJI  
FT-05FL




Figure 4. Secondary PCB with UWB Radio #2 and Disabled 2.4 GHz radio

US Tech Test Report:  
FCC ID:  
Test Report Number:  
Issue Date:  
Customer:  
Model:

FCC Part 15 Certification  
2AUF1-FT-05FL  
19-0287  
November 5, 2019  
OKYANUS TEKNOLOJI  
FT-05FL

---



**Figure 5. Flex Patch 2.4 GHz Antenna (5 GHz Band not used with this Radio)**