

**GENERAL INFORMATION**

 Change Date: **Wednesday, July 10, 2019**

 Change Reference  
 No:

**PCN19191-01**

 Products  
 Affected:

**ISM43362-M3G-L44-E  
 and -U**
**TYPE OF CHANGE**
 **Product**     
  **Process**     
  **Specification**     
  **Marking**
**CHANGE ORDER JUSTIFICATION AND DESCRIPTION**

 Laser Marking is used for the P/N and FCC and IC Certification Grant Numbers.  
 Modified Date code label to identify E or U Option.

Laser Stencil:

**ISM43362**  
**FCC ID : O7P-362**  
**IC : 10147A-362**

High Temperature Date Code label :

**1925 E**      (YY=Last two Digits of the Year)  
**YYWWX**      (WW=Digits for the workweek)  
                   (E for Etched antenna)  
                   (U for U.FL Connector for External Antenna)

**SUPPORTING DATA**

Recommended Replacement product:

Not Applicable

**IDENTIFICATION OF CHANGED PRODUCT**
**ISM43362-M3G-L44-E**  
**ISM43362-M3G-L44-U**
**CHANGE CLASSIFICATION**
 **Minor**
 **Major**
**CUSTOMER FEEDBACK**

 Please acknowledge receipt of this change note by replying to [sales@inventeksys.com](mailto:sales@inventeksys.com)

 When you have reviewed the information, please reply to [sales@inventeksys.com](mailto:sales@inventeksys.com) to confirm acceptance of the change, or requesting further information.

If no communication is received within 30 days of the date of this notification, Inventek may accept that this change has been received and can implement the change as indicated above.