


Report No.: EED32P80467601 Page 32 of 53

10 PHOTOGRAPHS OF EUT Constructional Details



View of Product-1



View of Product-2















Report No.: EED32P80467601 Page 33 of 53



View of Product-3



View of Product-4

Complaint call:0755-33681700















Report No.: EED32P80467601 Page 34 of 53



View of Product-5



View of Product-6














Report No.: EED32P80467601 Page 35 of 53



View of Product-7



View of Product-8















Report No. : EED32P80467601 Page 36 of 53



View of Product-9



View of Product-10













Report No.: EED32P80467601 Page 37 of 53



View of Product-11



View of Product-12














Report No.: EED32P80467601 Page 38 of 53



View of Product-13



View of Product-14














Report No. : EED32P80467601 Page 39 of 53



View of Product-15



View of Product-16
















Report No.: EED32P80467601 Page 40 of 53



View of Product-17



View of Product-18











Report No.: EED32P80467601 Page 41 of 53



View of Product-19



View of Product-20













Report No. : EED32P80467601 Page 42 of 53



View of Product-21



View of Product-22













Report No. : EED32P80467601 Page 43 of 53



View of Product-23



View of Product-24













Report No. : EED32P80467601 Page 44 of 53



