C.O.B.O SpA Via Tito Speri, 10 Leno (BS) Italy

Applicant:

C.O.B.O. Spa

Model Differences Letter

| IC: 25864-04610184 |
|---|
| FCC: 2AVOV-04610184 |
| mod. 04610184 |
| The 1406 family of products for North America market is composed by following HVINs: |
| ✓ 04610184✓ 04610196✓ 04610233 |
| The only difference between them is: |
| 04610184 Main model. See <u>04610184-drw.pdf</u> |
| 04610196 The same as the Main model but without DRL function and without L13 LED. See 04610196.pdf |
| 04610233 The same as the Main model but without DRL function and without L13 LED. See 04610233.pdf |
| All three HVINs have same hardware, same enclosure, same radio features. A daytime running lamp (DRL, also daytime running light) is an automotive lighting device on the front of a road-going motor vehicle. The differences between 04610196 and 04610233 are related to application software. |
| DRL function and application software are not relevant for testing so only model 04610184 has been tested. |
| Dated this 19 Day of February 20 20 |
| By: Wolfango Cozzi |
| Signature Printed |
| Title: President |
| Telephone: +39 0309045201 |