

INTERTEK TESTING SERVICE


Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Powered by Notebook USB Port + 2.4GHz Operating



INTERTEK TESTING SERVICE

Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

Powered by Notebook USB Port + 2.4GHz Operating



INTERTEK TESTING SERVICE


Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Powered by Notebook USB Port + 2.4GHz Operating



INTERTEK TESTING SERVICE


Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

Powered by Notebook USB Port + 2.4GHz Operating



INTERTEK TESTING SERVICE


Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Powered by Notebook USB Port + 2.4GHz Operating with Docking
(Cradle)



INTERTEK TESTING SERVICE

Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

**Powered by Notebook USB Port + 2.4GHz Operating with Docking
(Cradle)**



INTERTEK TESTING SERVICE


Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

**Powered by Notebook USB Port + 2.4GHz Operating with Docking
(Cradle)**



INTERTEK TESTING SERVICE

Report No: HK21070499

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

**Powered by Notebook USB Port + 2.4GHz Operating with Docking
(Cradle)**

