Report No: HK21070499

## **Configuration Photographs**

## Worst-Case Line-Conducted Emissions

(Front View)

#### Powered by Notebook USB Port + 2.4GHz Operating



Report No: HK21070499

**Configuration Photographs** 

# Worst-Case Line-Conducted Emissions

(Rear View)

# Powered by Notebook USB Port + 2.4GHz Operating



Report No: HK21070499

**Configuration Photographs** 

# Worst-Case Line-Conducted Emissions

(Side View)

# Powered by Notebook USB Port + 2.4GHz Operating



Report No: HK21070499

#### **Configuration Photographs**

#### Worst-Case Line-Conducted Emissions

(Front View)

# Powered by Notebook USB Port + 2.4GHz Operating with Docking (Cradle)



Report No: HK21070499

#### **Configuration Photographs**

#### Worst-Case Line-Conducted Emissions

(Rear View)

Powered by Notebook USB Port + 2.4GHz Operating with Docking (Cradle)



Report No: HK21070499

#### **Configuration Photographs**

## Worst-Case Line-Conducted Emissions

(Side View)

Powered by Notebook USB Port + 2.4GHz Operating with Docking (Cradle)

