




Disassembly Top View

software development & electronics design

ph 401.461.1484
fax 401.461.1218
web www.baycomp.com
email info@baycomp.com
Bay Computer Associates, Inc.
136 Frances Avenue ▶ Cranston, RI 02910

c o n f i d e n t i a l



Disassembly Bottom View

ph 401.461.1484

fax 401.461.1218

web www.baycomp.com

email info@baycomp.com

Bay Computer Associates, Inc.

136 Frances Avenue ▶ Cranston, RI 02910

software development & electronics design

c o n f i d e n t i a l



Disassembly Front View

software development & electronics design

ph 401.461.1484
fax 401.461.1218
web www.baycomp.com
email info@baycomp.com
Bay Computer Associates, Inc.
136 Frances Avenue ▶ Cranston, RI 02910

c o n f i d e n t i a l



Disassembly Right Side View

ph 401.461.1484

fax 401.461.1218

web www.baycomp.com


email info@baycomp.com

Bay Computer Associates, Inc.

136 Frances Avenue ▶ Cranston, RI 02910

software development & electronics design

c o n f i d e n t i a l




Disassembly Back View

software development & electronics design

ph 401.461.1484
fax 401.461.1218
web www.baycomp.com
email info@baycomp.com
Bay Computer Associates, Inc.
136 Frances Avenue ▶ Cranston, RI 02910

c o n f i d e n t i a l



Disassembly Back Revealed View

software development & electronics design

ph 401.461.1484
fax 401.461.1218
web www.baycomp.com
email info@baycomp.com
Bay Computer Associates, Inc.
136 Frances Avenue ▶ Cranston, RI 02910

c o n f i d e n t i a l




Disassembly Left Side View

software development & electronics design

ph 401.461.1484
fax 401.461.1218
web www.baycomp.com
email info@baycomp.com
Bay Computer Associates, Inc.
136 Frances Avenue ▶ Cranston, RI 02910

c o n f i d e n t i a l



Main PCB (in Device)

ph 401.461.1484

fax 401.461.1218

web www.baycomp.com


email info@baycomp.com

Bay Computer Associates, Inc.


136 Frances Avenue ▶ Cranston, RI 02910

software development & electronics design

c o n f i d e n t i a l



Top Board Removed/Solenoid exposed



Main Board Front

ph 401.461.1484

fax 401.461.1218

web www.baycomp.com


email info@baycomp.com

Bay Computer Associates, Inc.

136 Frances Avenue ▶ Cranston, RI 02910

software development & electronics design

c o n f i d e n t i a l



Main Board Back

ph 401.461.1484

fax 401.461.1218

web www.baycomp.com


email info@baycomp.com

Bay Computer Associates, Inc.

136 Frances Avenue ▶ Cranston, RI 02910

software development & electronics design

c o n f i d e n t i a l



Bottom Revealed

ph 401.461.1484

fax 401.461.1218

web www.baycomp.com


email info@baycomp.com

Bay Computer Associates, Inc.

136 Frances Avenue ▶ Cranston, RI 02910

software development & electronics design

c o n f i d e n t i a l



Auxiliary Board Front

ph 401.461.1484

fax 401.461.1218

web www.baycomp.com


email info@baycomp.com

Bay Computer Associates, Inc.

136 Frances Avenue ▶ Cranston, RI 02910

software development & electronics design

c o n f i d e n t i a l



Auxiliary Board Back




Flex Circuit/RFID Antenna

software development & electronics design

ph 401.461.1484
fax 401.461.1218
web www.baycomp.com
email info@baycomp.com
Bay Computer Associates, Inc.
136 Frances Avenue ▶ Cranston, RI 02910

c o n f i d e n t i a l



Main Board connected to Auxiliary Board

ph 401.461.1484

fax 401.461.1218

web www.baycomp.com

email info@baycomp.com

Bay Computer Associates, Inc.

136 Frances Avenue ▶ Cranston, RI 02910

software development & electronics design

c o n f i d e n t i a l