

# INTERTEK TESTING SERVICE


---

Report No: HK21081567

## Configuration Photographs

### Worst-Case Radiated Emissions

**(Front View)**



---

---


# INTERTEK TESTING SERVICE

Report No: HK21081567

## Configuration Photographs

### Worst-Case Radiated Emissions

**(Rear View)**



# INTERTEK TESTING SERVICE

Report No: HK21081567

## Configuration Photographs

### Worst-Case Radiated Emissions

**(Front View)**




# INTERTEK TESTING SERVICE

Report No: HK21081567

## Configuration Photographs

### Worst-Case Radiated Emissions

**(Rear View)**



# INTERTEK TESTING SERVICE

---

Report No: HK21081567

## Configuration Photographs

### Worst-Case Radiated Emissions

**(Front View)**



---

---

# INTERTEK TESTING SERVICE

---

Report No: HK21081567

## Configuration Photographs

### Worst-Case Radiated Emissions

**(Rear View)**

**Base Station wifi and Bluetooth BLE Operating**



---

# INTERTEK TESTING SERVICE

---


Report No: HK21081567

## Configuration Photographs

### Worst-Case Radiated Emissions

(Front View)

Base Station wifi and Bluetooth BLE Operating



---

---

# INTERTEK TESTING SERVICE


---

Report No: HK21081567

## Configuration Photographs

### Worst-Case Radiated Emissions

**(Rear View)**



---

---