


Setup Photos


Revision	Report Date	Reason for Revision
∅	June 29, 2021	Initial Issue.
1	August 12, 2021	Review Updates



Radiated Spurious Emissions, 1GHz – 18GHz, Test Setup




Radiated Spurious Emissions, 1GHz – 18GHz, Test Setup



Substitution Method, Test Setup



OTA EIRP Test Setup View 1



OTA EIRP Test Setup View 2