

Page : 1 of 14 Issued date : Sep. 5, 2022

External Photos Group Pic 1



Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948



Page : 2 of 14 Issued date : Sep. 5, 2022

Outview: T310 Pic 1



Outview: T310 Pic 2



Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948



Test report No. : 4790458118-EP Page : 3 of 14

Issued date : Sep. 5, 2022

Outview: T310 Pic 3



Outview: T310 Pic 4



Underwriters Laboratories Taiwan Co., Ltd.
Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000

Facsimile (FAX) :+886-3-583-7948




Page : 4 of 14 Issued date : Sep. 5, 2022

Outview: T310 Pic 5







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948



Page : 5 of 14 Issued date : Sep. 5, 2022

Accessory: Battery (CR2450) Pic 1



Accessory: Battery (CR2450) Pic 2



Underwriters Laboratories Taiwan Co., Ltd.Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

:+886-2-7737-3000 Telephone Facsimile (FAX) :+886-3-583-7948



Page : 6 of 14 Issued date : Sep. 5, 2022

Accessory: Battery (CR2450) Pic 3



Facsimile (FAX) :+886-3-583-7948