



## 60TR13EM011 Firmware

Host manufacturer cannot modify the firmware for following reasons:

- The JTAG of the MCU in the radar module is locked. It is not possible to access or change the firmware inside the flash using JLINK.
- The firmware file is encrypted; direct change to the file will corrupt the file. Bootloader inside the module will check the validity of the file before doing firmware update.

*Dr. Waldemar Marsetz*

Dr. Waldemar Marsetz

04.03.2021

**Infineon Technologies AG**

Postal address D-81726 München Internet [www.infineon.com](http://www.infineon.com) Headquarters Am Campeon 1-15, D-85579 Neuburg Phone +49 (0)89 234-0

Chairman of the Supervisory Board Dr. Wolfgang Eder

Management Board Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider

Registered office Neuburg Commercial register Amtsgericht München HRB 126492