

TP-LINK CORPORATION PTE.LTD.

Federal Communications Commission
7435 Oakland Mills Road
Columbia MD 21046

American Certification Body, Inc.
6731 Whittier Avenue
Suite C110
McLean, VA 22101

Subject: Requesting Class II permissive change for FCC ID: 2BCGWS500

To Whom It May Concern:

The purpose of this letter is to request a Class II Permissive change for FCC ID: 2BCGWS500, original granted on 11/30/2023.


There is no other hardware or electrical modification made to the applying transmitter itself except below:

The worst cases of conducted and radiated emissions below 1GHz have been re-evaluated by sample of FCC ID: 2BCGWS500, model name: HS200-2. It is found that the new data are the worse, so the test data are reissue from the FCC ID: 2AXJ4S500, model name: Tapo S500.

Model difference(s):

- a. Changed the model name as HS200-2. (HS200-2 consists of original model Tapo S500*2 and an outer frame, functions and circuits are independent.)
- b. Changed the information of applicant and manufacturer.
- c. Changed the shell.
- d. Changed the power rating.

Please refer to the following picture.



The product of HS220-2 is sold together with two HS220s, and the following panels are provided for users to arrange on their home walls.

Both HS220s operate in client mode and are remotely controlled by users through the app. The WiFi function is used to control the on and off of switches, with no other data exchange functions included. And they work independently, including configuration and working status, all of which are independent of the other one.

Please contact me if you have any questions or need further information regarding this application.

Best Regards,

Name: Sarah Wang

Funtion: Regulatory Compliance Manager

Date: 2024-01-25

Signed :

Sarah Wang