




11N40SISO_Ant1_5190




11N40SISO_Ant1_5230




11N40SISO_Ant1_5755




11N40SISO_Ant1_5795




11AC20SISO_Ant1_5180




11AC20SISO_Ant1_5200






11AC20SISO_Ant1_5240




11AC20SISO_Ant1_5745




11AC20SISO_Ant1_5785







11AC40SISO_Ant1_5755



11AC40SISO_Ant1_5795




11AX20SISO_Ant1_5180




Date: 13.JUN.2024 21:31:47

11AX20SISO_Ant1_5200




Date: 13.JUN.2024 21:35:46

11AX20SISO_Ant1_5240




Date: 13.JUN.2024 21:38:08

11AX20SISO_Ant1_5745




Date: 13.JUN.2024 21:41:56

11AX20SISO_Ant1_5785




Date: 13.JUN.2024 21:45:50

11AX20SISO_Ant1_5825




Date: 13.JUN.2024 21:49:13


11AX40SISO_Ant1_5190




11AX40SISO_Ant1_5230



11AX40SISO_Ant1_5755



11AX40SISO_Ant1_5795



-----End of the report-----