Typhur Inc.

2890 Zanker Road #120, San Jose, CA 95134, USA

Date: 02/01/2024

FCC Laboratory 7435 Oakland Mills Rd Columbia MD 21046

Certification and Engineering Bureau ISED Canada 3701 Carling Avenue (Building 94) Ottawa, Ontario K2H 8S2

To whom it may concern,

This application for Change of Identification request a new FCC ID and IC ID as stipulated in 47 CFR 2.933 (b) and RSP-100 for presently authorized equipment.

This application by <u>Typhur Inc.</u> will establish a new FCC ID: 2BEFM-WT1000R, a new IC: 31884-WT1000R, PMN: WT1000R, HVIN: WT1000R, FVIN: v1.1.3.4 for the purpose of marketing.

The original grant to ESPRESSIF SYSTEMS (SHANGHAI) CO., LTD.

FCC ID: 2AC7Z-ESPS3WROOM1U, granted on 03/31/2022.

IC: 21098-ESPS3WROOMU, PMN: ESP32-S3-WROOM-1U, HVIN: ESP32-S3-WROOM-1U,

FVIN: v1.1.3.4, granted on 04/11/2022. Will remain in effect.

Per 47 CFR 2.933(b)/RSP-100

- The original identification is FCC ID: 2AC7Z-ESPS3WROOM1U and IC: 21098-ESPS3WROOMU
- 2. The original grant date is 03/31/2022 for FCC ID and date is 04/11/2022 for IC ID.
- 3. The equipment is electrically identical. Only the trade name and FCC ID number are different.
- 4. The original test results continue to be representative of and applicable to the equipment bearing the changed identification.
- 5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

- Cover Letter
- External Photos
- FCC ID label format and location

User Manual

Should there be any question, please feel free to contact us. Sincerely,

Applicant Signature

Wilson Arrang

Printed Name: Wilson Huang Title: Certification Engineer

Email: wilson.huang@typhur.com