

04/09/2024

Federal Communications Commission  
Equipment Authorization Branch  
7435 Oakland Mills Road  
Columbia, MD 21046

Re: Part 2.933 Change in Identification to FCC ID: 2BFJB-ESPC3MINI1

To Whom It May Concern:

I hereby request a change in identification in accordance to CFR 47 Part 2.933 of the FCC rules. The original identification used on the equipment prior to this application for Change in Identification is 2AC7Z-ESPC3MINI1. The date of the original grant of the equipment authorization is 06/16/2021.

I certify that the equipment bearing the modified identification, FCC ID: 2BFJB-ESPC3MINI1 does not differ from the original equipment.

I further certify that the original test results continue to be representative of and applicable to the equipment bearing the changed identification.

Sincerely,  
Gordon Warr



Engineering Manager

Sensidyne, LP

1000 112<sup>th</sup> Circle North  
Suite 100  
St. Petersburg, FL 33716  
U.S.A.

T 800-451-9444  
T +1 727-530-3602  
F +1 727-539-0550

Email: [info@Sensidyne.com](mailto:info@Sensidyne.com)  
[www.Sensidyne.com](http://www.Sensidyne.com)  
[www.Schauenburg.com](http://www.Schauenburg.com)

