

GROUP WORK	SUB GROUP	RELEASED FOR	PRODUCTION
	857044		12-07-59

AA
1/2, 2/2 pass
Change 377 (A-3)
Change 377 (B)
Change Block copy (A-3)
Change Block copy (B-5)
Scale cover (D-5)
K. ITO / H. FUJIHARA
01-13-00
K. YABUKI / H. FUJIHARA
EN-301133

AB
1/2, 2/2 pass
Change P/N (A-3)
Y01/Y05 Change P/N (B-2)
Y01/Y05 Change P/N (C-2)
Y01/Y05 Change Paris (A-3)
KNOB BAUS/TREB
Change P/N (A-3)
Change P/N (B-2)
Change P/N (C-2)
Y03: 56038585AD-56038585AD
Y03: 56038585AA-56038585AD
Y03: 56038585AB-56038585AB
Y03: 56038585AC-56038585AC
K. ITO / H. FUJIHARA
07-14-00
K. YABUKI / H. FUJIHARA
EN-301133

AC
1/2 pass
Change P/N (A-3)
Change P/N (B-2)
Change P/N (C-2)
Add 1 inch roller
2/2 pass
Add Y05 (C-5, E-2)
07-31-00
K. YABUKI / H. FUJIHARA
EN-301133


AD
1/2 pass
Add LABEL E-MARK (E-3)
Change P/N (B-2)
Change P/N (B-2)
Y03: 56038585AD-56038585AE
Y05: 56038585AD-56038585AE
K. ITO / H. FUJIHARA
08-29-00
K. YABUKI / H. FUJIHARA
EN-301133

AE
2/2 pass Move LABEL ANTI-THEFT
K. ITO / H. FUJIHARA
10-12-00
K. YABUKI / H. FUJIHARA
EN-301133

AF
1/2 pass
Add LABEL C-TICK MARK (E-3)
Add TABLE (F-6)
K. ITO / H. FUJIHARA
10-23-00
K. YABUKI / H. FUJIHARA
EN-301133

AG
2/2 pass
Change P/N (B-3, 8)
J. NAITSUJI / H. FUJIHARA
11-13-00
K. YABUKI / H. FUJIHARA
EN-301133

AH
1/2 pass
Change Block copy
CD/CD-C-MODE (C-8)
2/2 pass
Change Block copy
K. ITO / H. FUJIHARA
12-27-00
K. YABUKI / H. FUJIHARA
EN-301133



NOTE--
1. ~ ~ are important controlled dimension which are same as measurement points of annual layout. Measurement of dimensional data should be use assembled production with setting by exclusive jig.