



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

January 11, 2008

RE: FCC ID: A269ZUA127_ATCB005821
Attention: Yuki Morimoto / Norihisa Hashimoto

I have a few comments on this Application. Please note that further comments may arise in response to answers provided to the questions below.

1. Please note that page 10 of the data portion of the report states that the antenna cable loss was provided by the client and included in the total cable loss factor. Please note that losses used in direct relation to a measurement cannot be assumed and must have supporting evidence. Please either measure the conducted power directly at the antenna connection (i.e. after the client provided cable) or please provide the calibration factors from the manufacturer on the cable used to support the data.
2. Please note that the FCC ID label appears to be a simple paper printed label possibly glued to the shield of the main board. Please note that if this is true it is not allowed by the FCC. Please provide an explanation of what the label is made of and how it is permanently affixed to the device as required by 2.925(d).

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.