

"Dward ATCB" <dward@atcb.com>

To <Yuki.Morimoto@jp.ul.com>

2008/01/12 05:34

cc

Subject RE: www.AmericanTCB.com ATCB005820 | A269ZUA128 | 700B - 09386Z | | A269ZUA128_ATCB005820

Please respond to
<dward@atcb.com>

Hi Yuki

Disregard the comment about Modular approval. I found the modular request letter. Some how it did not download to my computer and I had to find it on the server, but only after I sent the comments. Again, please disregard the comment about modular approval. The other comments are still needed to have responses provided.

Thanks

Dennis Ward
Director of Engineering
American TCB
Certification Resource for the Wireless Industry www.atcb.com
703-847-4700 fax 703-847-6888
direct - 703-880-4841

NOTICE: This E-Mail message and any attachment may contain privileged or company proprietary information. If you received this message in error, please return to the sender.

From: Dward ATCB [<mailto:dward@atcb.com>]
Sent: 01/11/2008 12:18 PM
To: 'Yuki.Morimoto@jp.ul.com'
Cc: 'customerservice@atcb.com'
Subject: www.AmericanTCB.com ATCB005820 | A269ZUA128 | 700B - 09386Z | | A269ZUA128_ATCB005820

Regarding www.AmericanTCB.com application:
ATCB ID: ATCB005820
FCC ID: A269ZUA128
IC: 700B - 09386Z
TCF:

01/21/08

Account name: yukimorimoto

Hi Yuki

Please see comments

Thanks

Dennis Ward

- For more information about UL, its Marks, and its services for EMC, quality registrations and product certifications for global markets, please access our web sites at <http://www.ul.com> and <http://www.ul-asia.com> or contact your local sales representative. --

***** Internet E-mail Confidentiality Disclaimer *****
This e-mail message may contain privileged or confidential information. If you are not the intended recipient, you may not disclose, use, disseminate, distribute, copy or rely upon this message or attachment in any way. If you received this e-mail message in error, please return by forwarding the message and its attachments to the sender.

UL and its affiliates do not accept liability for any errors, omissions, corruption or virus in the contents of this message or any attachments.
