

# INTERTEK TESTING SERVICE


---

Report No.: HK12090539-1

## Equipment Photographs

Model: PA5075U-1SPA

(Internal)



---

# INTERTEK TESTING SERVICE


---

Report No.: HK12090539-1

## Equipment Photographs

Model: PA5075U-1SPA

(Internal)



# INTERTEK TESTING SERVICE



---

Report No.: HK12090539-1

## Equipment Photographs

Model: PA5075U-1SPA

(Internal)







# INTERTEK TESTING SERVICE

Report No.: HK12090539-1

## Equipment Photographs

Model: PA5075U-1SPA

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK12090539-1

## Equipment Photographs

Model: PA5075U-1SPA

(Internal)




# INTERTEK TESTING SERVICE

Report No.: HK12090539-1

## Equipment Photographs

Model: PA5075U-1SPA

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK12090539-1

## Equipment Photographs

Model: PA5075U-1SPA

(Internal)





---

## INTERTEK TESTING SERVICE


---

Report No.: HK12090539-1

### Equipment Photographs

Model: PA5075U-1SPA

(Internal)



# INTERTEK TESTING SERVICE

---

Report No.: HK12090539-1

## Equipment Photographs

Model: PA5075U-1SPA

(Internal)

