

# INTERTEK TESTING SERVICE


---

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)




# INTERTEK TESTING SERVICE

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)



FCC ID: A2HRCT6293W23  
IC: 9903A-RCT6293W23

---

# INTERTEK TESTING SERVICE



---

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)



---

FCC ID: A2HRCT6293W23  
IC: 9903A-RCT6293W23

# INTERTEK TESTING SERVICE

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)



# INTERTEK TESTING SERVICE

---

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)



# INTERTEK TESTING SERVICE

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)



# INTERTEK TESTING SERVICE


---

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)



---

# INTERTEK TESTING SERVICE


---

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)





# INTERTEK TESTING SERVICE



---

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)



# INTERTEK TESTING SERVICE



---

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)



# INTERTEK TESTING SERVICE



---

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)





# INTERTEK TESTING SERVICE



---

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)



---

FCC ID: A2HRCT6293W23  
IC: 9903A-RCT6293W23



# INTERTEK TESTING SERVICE

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)



FCC ID: A2HRCT6293W23

IC: 9903A-RCT6293W23

# INTERTEK TESTING SERVICE


---

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)



# INTERTEK TESTING SERVICE

---

Report No.: 14080215HKG-002

## Equipment Photographs

Model: CT9293W23

(Internal)

