

---

# INTERTEK TESTING SERVICE


---

Report No.: HK12060155-1

## Equipment Photographs

Model: CD2965SB

(Internal)



---

# INTERTEK TESTING SERVICE



---

Report No.: HK12060155-1

## Equipment Photographs

Model: CD2965SB

(Internal)



# INTERTEK TESTING SERVICE



---

Report No.: HK12060155-1

## Equipment Photographs

Model: CD2965SB

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK12060155-1

## Equipment Photographs

Model: CD2965SB

(Internal)




# INTERTEK TESTING SERVICE

Report No.: HK12060155-1

## Equipment Photographs

Model: CD2965SB

(Internal)



# INTERTEK TESTING SERVICE

Report No.: HK12060155-1

## Equipment Photographs

Model: CD2965SB

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK12060155-1

## Equipment Photographs

Model: CD2965SB

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK12060155-1

## Equipment Photographs

Model: CD2965SB

(Internal)





---

# INTERTEK TESTING SERVICE


---

Report No.: HK12060155-1

## Equipment Photographs

Model: CD2965SB

(Internal)



# INTERTEK TESTING SERVICE

---

Report No.: HK12060155-1

## Equipment Photographs

Model: CD2965SB

(Internal)

