

---

# INTERTEK TESTING SERVICE

---

Report No.: HK12051434-2

## Equipment Photographs

Model: SBX4250KN

(Internal)



# INTERTEK TESTING SERVICE


---

Report No.: HK12051434-2

## Equipment Photographs

Model: SBX4250KN

(Internal)



---

# INTERTEK TESTING SERVICE



---

Report No.: HK12051434-2

## Equipment Photographs

Model: SBX4250KN

(Internal)





# INTERTEK TESTING SERVICE



---

Report No.: HK12051434-2

## Equipment Photographs

Model: SBX4250KN

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK12051434-2

## Equipment Photographs

Model: SBX4250KN

(Internal)





# INTERTEK TESTING SERVICE



---

Report No.: HK12051434-2

## Equipment Photographs

Model: SBX4250KN

(Internal)





# INTERTEK TESTING SERVICE

Report No.: HK12051434-2

## Equipment Photographs

Model: SBX4250KN

(Internal)







# INTERTEK TESTING SERVICE

Report No.: HK12051434-2

## Equipment Photographs

Model: SBX4250KN

(Internal)



FCC ID: A2HSBX4250KN

IC: 9903A-SBX4250KN