



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (454) / (2355)
Pages

ANT 45

QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (455) / (2355)
Pages

ANT 46


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (456) / (2355)
Pages

ANT 47

QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (457) / (2355)
 Pages

ANT 48

QPSK



16QAM



64QAM



256QAM





ANT 49

QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (459) / (2355)
 Pages

ANT 50

QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (460) / (2355)
 Pages

ANT 51

QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (461) / (2355)
 Pages

ANT 52

QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (462) / (2355)
 Pages

ANT 53


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2020-04662
Page (463) / (2355)
Pages

ANT 54


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (464) / (2355)
Pages

ANT 55

QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2020-04662
Page (465) / (2355)
Pages

ANT 56

QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (466) / (2355)
Pages

ANT 57

QPSK



16QAM



64QAM



256QAM



ANT 58


QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (468) / (2355)
Pages

ANT 59

QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (469) / (2355)
 Pages

ANT 60

QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (470) / (2355)
Pages

ANT 61

QPSK



16QAM



64QAM



256QAM



ANT 62

QPSK



16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (472) / (2355)
Pages

ANT 63

QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (473) / (2355)
Pages

ANT 64


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (474) / (2355)
 Pages

**BW 100 MHz + 100 MHz, Multi carrier(Non-contiguous), Top(2nd FA CC1)
 ANT 1**

QPSK

16QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2020-04662
Page (475) / (2355)
Pages

ANT 2

QPSK

16QAM






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501


Report No.:
CTK-2020-04662
Page (476) / (2355)
Pages

ANT 3


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (477) / (2355)
 Pages

ANT 4

QPSK




16QAM



64QAM



256QAM







ANT 5



QPSK

16QAM



64QAM

256QAM






ANT 6



QPSK

16QAM



64QAM

256QAM







ANT 7



QPSK

16QAM



64QAM

256QAM







ANT 8



QPSK

16QAM



64QAM

256QAM






ANT 9



QPSK

16QAM



64QAM

256QAM






ANT 10

QPSK


16QAM






ANT 11


QPSK




16QAM



64QAM



256QAM







ANT 12


QPSK

16QAM



64QAM

256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (486) / (2355)
 Pages

ANT 13



QPSK

16QAM



64QAM

256QAM







ANT 14



QPSK

16QAM



64QAM

256QAM







ANT 15



QPSK

16QAM



64QAM

256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (489) / (2355)
 Pages

ANT 16



QPSK

16QAM



64QAM

256QAM







ANT 17


QPSK

16QAM



64QAM

256QAM







ANT 18



QPSK

16QAM



64QAM

256QAM







ANT 19



QPSK

16QAM



64QAM

256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (493) / (2355)
 Pages

ANT 20



QPSK

16QAM



64QAM

256QAM





ANT 21


QPSK




16QAM



64QAM



256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (495) / (2355)
 Pages

ANT 22



QPSK

16QAM



64QAM

256QAM







ANT 23



QPSK

16QAM



64QAM

256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (497) / (2355)
 Pages

ANT 24



QPSK

16QAM



64QAM

256QAM







ANT 25



QPSK

16QAM



64QAM

256QAM







CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (499) / (2355)
 Pages

ANT 26



QPSK

16QAM



64QAM

256QAM







ANT 27



QPSK

16QAM



64QAM

256QAM







ANT 28

QPSK

16QAM



64QAM



256QAM



ANT 29



QPSK

16QAM



64QAM

256QAM






ANT 30

QPSK

16QAM







ANT 31


QPSK

16QAM



64QAM

256QAM







ANT 32

QPSK

16QAM



64QAM

256QAM

