



ANT25


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (770) / (2355)
 Pages

ANT26


QPSK




16QAM



64QAM




256QAM



ANT27

QPSK




16QAM



64QAM




256QAM




ANT28


QPSK




16QAM



64QAM




256QAM




ANT29


QPSK




16QAM



64QAM




256QAM




ANT30


QPSK



16QAM



64QAM




256QAM




ANT31

QPSK




16QAM



64QAM




256QAM






ANT32


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (777) / (2355)
 Pages

ANT33


QPSK




16QAM



64QAM




256QAM



ANT34

QPSK

16QAM






ANT35

QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (780) / (2355)
 Pages

ANT36


QPSK



16QAM



64QAM




256QAM




ANT37


QPSK



16QAM



64QAM




256QAM



ANT38


QPSK




16QAM



64QAM




256QAM






ANT39


QPSK




16QAM



64QAM




256QAM




ANT40


QPSK




16QAM



64QAM




256QAM



ANT41


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (786) / (2355)
 Pages

ANT42


QPSK

16QAM




ANT43


QPSK



16QAM



64QAM




256QAM






ANT44


QPSK



16QAM



64QAM




256QAM




ANT45


QPSK




16QAM



64QAM




256QAM




ANT46


QPSK




16QAM



64QAM




256QAM




ANT47


QPSK



16QAM



64QAM




256QAM




ANT48


QPSK



16QAM



64QAM




256QAM






ANT49


QPSK




16QAM



64QAM




256QAM




ANT50


QPSK



16QAM



64QAM




256QAM






ANT51

QPSK




16QAM



64QAM




256QAM






ANT52


QPSK




16QAM



64QAM



256QAM






ANT53


QPSK

16QAM




ANT54


QPSK



16QAM



64QAM




256QAM






ANT55


QPSK



16QAM



64QAM




256QAM




ANT56


QPSK



16QAM



64QAM




256QAM




ANT57


QPSK




16QAM



64QAM




256QAM



ANT58


QPSK



16QAM



64QAM




256QAM




ANT59


QPSK




16QAM



64QAM




256QAM




ANT60


QPSK



16QAM



64QAM




256QAM






ANT61


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (806) / (2355)
 Pages

ANT62


QPSK



16QAM



64QAM




256QAM




ANT63


QPSK



16QAM



64QAM




256QAM





ANT64


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (809) / (2355)
 Pages

**BW 100MHz, Single carrier, Middle
 ANT1**


QPSK



16QAM



64QAM



256QAM






ANT2

QPSK


16QAM






ANT3

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (812) / (2355)
 Pages

ANT4

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (813) / (2355)
 Pages

ANT5

QPSK


16QAM






ANT6


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (815) / (2355)
 Pages

ANT7

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (816) / (2355)
 Pages

ANT8


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (817) / (2355)
 Pages

ANT9


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (818) / (2355)
 Pages

ANT10


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (819) / (2355)
 Pages

ANT11


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (820) / (2355)
 Pages

ANT12

QPSK




16QAM



64QAM




256QAM






ANT13


QPSK



16QAM



64QAM



256QAM

