



**ANT47**


**QPSK**




**16QAM**



**64QAM**



**256QAM**



**ANT48**

**QPSK**



**16QAM**



**64QAM**



**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (985) / (2355)  
 Pages

**ANT49**

**QPSK**

**16QAM**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (986) / (2355)  
 Pages

**ANT50**

**QPSK**



**16QAM**



**64QAM**




**256QAM**






**ANT51**


**QPSK**




**16QAM**



**64QAM**



**256QAM**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (988) / (2355)  
 Pages

**ANT52**

**QPSK**



**16QAM**



**64QAM**



**256QAM**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (989) / (2355)  
 Pages

**ANT53**

**QPSK**



**16QAM**



**64QAM**




**256QAM**




**ANT54**


**QPSK**




**16QAM**



**64QAM**



**256QAM**








**ANT55**


**QPSK**




**16QAM**



**64QAM**



**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (992) / (2355)  
 Pages

**ANT56**

**QPSK**

**16QAM**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (993) / (2355)  
 Pages

**ANT57**

**QPSK**




**16QAM**



**64QAM**



**256QAM**





**ANT58**


**QPSK**



**16QAM**



**64QAM**



**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2020-04662  
 Page (995) / (2355)  
 Pages

**ANT59**

**QPSK**




**16QAM**



**64QAM**



**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (996) / (2355)  
 Pages

**ANT60**

**QPSK**

**16QAM**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (997) / (2355)  
 Pages

**ANT61**

**QPSK**



**16QAM**



**64QAM**



**256QAM**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (998) / (2355)  
 Pages

**ANT62**

**QPSK**




**16QAM**



**64QAM**



**256QAM**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (999) / (2355)  
 Pages

**ANT63**

**QPSK**



**16QAM**



**64QAM**




**256QAM**






**ANT64**


**QPSK**




**16QAM**



**64QAM**



**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (1001) / (2355)  
 Pages

**BW 100MHz + 100MHz, Multi carrier(Contiguous), Middle  
 ANT1**

QPSK


16QAM





**ANT2**


**QPSK**




**16QAM**



**64QAM**



**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2020-04662  
 Page (1003) / (2355)  
 Pages

**ANT3**


**QPSK**




**16QAM**



**64QAM**




**256QAM**






**ANT4**


**QPSK**




**16QAM**



**64QAM**



**256QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (1005) / (2355)  
 Pages

**ANT5**

*QPSK*

**16QAM**








**ANT6**

*QPSK*

**16QAM**








**ANT7**

*QPSK*

**16QAM**



*64QAM*


**256QAM**



**ANT8**

*QPSK*


*16QAM*



**ANT9**

*QPSK*


*16QAM*



**ANT10**

*QPSK*


**16QAM**






**ANT11**


**QPSK**




**16QAM**



**64QAM**




**256QAM**



**ANT12**


**QPSK**




**16QAM**



**64QAM**




**256QAM**



**ANT13**

*QPSK*


*16QAM*






**ANT14**


**QPSK**




**16QAM**



**64QAM**



**256QAM**








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (1015) / (2355)  
 Pages

**ANT15**

*QPSK*


*16QAM*



**ANT16**

*QPSK*


**16QAM**



**ANT17**

*QPSK*

**16QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (1018) / (2355)  
 Pages

**ANT18**

*QPSK*


*16QAM*



**ANT19**

*QPSK*

*16QAM*






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (1020) / (2355)  
 Pages

**ANT20**

*QPSK*

**16QAM**






**ANT21**

*QPSK*

**16QAM**








**ANT22**

*QPSK*

**16QAM**








**ANT23**

*QPSK*

**16QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (1024) / (2355)  
 Pages

**ANT24**

*QPSK*

**16QAM**






**ANT25**

*QPSK*


*16QAM*






**ANT26**


**QPSK**




**16QAM**



**64QAM**




**256QAM**





**ANT27**


**QPSK**




**16QAM**



**64QAM**




**256QAM**



**ANT28**

*QPSK*


*16QAM*






**ANT29**


**QPSK**




**16QAM**



**64QAM**



**256QAM**








**ANT30**

*QPSK*

*16QAM*






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (1031) / (2355)  
 Pages

**ANT31**

*QPSK*


*16QAM*



**ANT32**

*QPSK*

*16QAM*






**ANT33**

*QPSK*

*16QAM*






**ANT34**

*QPSK*

**16QAM**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2020-04662  
 Page (1035) / (2355)  
 Pages

**ANT35**

*QPSK*

**16QAM**



**ANT36**

*QPSK*

**16QAM**

