





ANT31


QPSK




16QAM



64QAM




256QAM



ANT32


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1161) / (2355)
 Pages

ANT33


QPSK




16QAM



64QAM



256QAM



ANT34

QPSK




16QAM



64QAM



256QAM




ANT35

QPSK




16QAM



64QAM




256QAM



ANT36

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1165) / (2355)
 Pages

ANT37


QPSK




16QAM



64QAM



256QAM






ANT38

QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1167) / (2355)
 Pages

ANT39


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1168) / (2355)
 Pages

ANT40


QPSK




16QAM



64QAM




256QAM




ANT41


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1170) / (2355)
 Pages

ANT42


QPSK




16QAM



64QAM




256QAM






ANT43


QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1172) / (2355)
 Pages

ANT44


QPSK




16QAM



64QAM




256QAM






ANT45


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1174) / (2355)
 Pages

ANT46


QPSK




16QAM



64QAM




256QAM



ANT47


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1176) / (2355)
 Pages

ANT48


QPSK




16QAM



64QAM




256QAM




ANT49


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1178) / (2355)
 Pages

ANT50


QPSK




16QAM



64QAM




256QAM




ANT51


QPSK




16QAM



64QAM




256QAM




ANT52


QPSK




16QAM



64QAM




256QAM






ANT53


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1182) / (2355)
 Pages

ANT54


QPSK




16QAM



64QAM



256QAM






ANT55


QPSK



16QAM



64QAM



256QAM






ANT56

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1185) / (2355)
 Pages

ANT57


QPSK




16QAM



64QAM



256QAM






ANT58


QPSK




16QAM



64QAM




256QAM






ANT59


QPSK



16QAM



64QAM



256QAM




ANT60

QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1189) / (2355)
 Pages

ANT61

QPSK




16QAM



64QAM



256QAM





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1190) / (2355)
 Pages

ANT62

QPSK




16QAM



64QAM



256QAM





ANT63


QPSK




16QAM



64QAM



256QAM



ANT64


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1193) / (2355)
 Pages

**BW 100MHz / 100MHz, Multi carrier(Non-contiguous), Top(2nd FA CC1)
 ANT1**






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1194) / (2355)
 Pages

ANT2

QPSK




16QAM



64QAM




256QAM



ANT3

QPSK

16QAM






ANT4

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1197) / (2355)
 Pages

ANT5

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1198) / (2355)
 Pages

ANT6

QPSK




16QAM



64QAM




256QAM






ANT7

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1200) / (2355)
 Pages

ANT8

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1201) / (2355)
 Pages

ANT9


QPSK




16QAM



64QAM




256QAM





ANT10


QPSK




16QAM



64QAM




256QAM





ANT11


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1204) / (2355)
 Pages

ANT12


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1205) / (2355)
 Pages

ANT13


QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1206) / (2355)
 Pages

ANT14

QPSK




16QAM



64QAM




256QAM



ANT15

QPSK




16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1208) / (2355)
 Pages

ANT16

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1209) / (2355)
 Pages

ANT17


QPSK



16QAM



64QAM



256QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2020-04662
 Page (1210) / (2355)
 Pages

ANT18

QPSK

16QAM






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2020-04662
 Page (1211) / (2355)
 Pages

ANT19


QPSK



16QAM



64QAM



256QAM

