




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (201) / (1312)  
 Pages

**ANT 2**  
**Band 2, BW 5MHz, Single carrier, 4TX, Bottom**

QPSK




16QAM



64QAM




256QAM






**Band 2, BW 5MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (203) / (1312)  
 Pages

**Band 2, BW 5MHz, Single carrier, 4TX, Top**


QPSK



16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (204) / (1312)  
 Pages

**ANT 3**  
**Band 2, BW 5MHz, Single carrier, 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (205) / (1312)  
 Pages

**Band 2, BW 5MHz, Single carrier, 4TX, Middle**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (206) / (1312)  
 Pages

**Band 2, BW 5MHz, Single carrier, 4TX, Top**

QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (207) / (1312)  
 Pages

**ANT 4**  
**Band 2, BW 5MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 5MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (209) / (1312)  
 Pages

**Band 2, BW 5MHz, Single carrier, 4TX, Top**


QPSK



16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (210) / (1312)  
 Pages

**ANT 1**  
**Band 2, BW 10MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**Band 2, BW 10MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (212) / (1312)  
 Pages

**Band 2, BW 10MHz, Single carrier, 4TX, Top**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (213) / (1312)  
 Pages

**ANT 2**  
**Band 2, BW 10MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (214) / (1312)  
 Pages

**Band 2, BW 10MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 10MHz, Single carrier, 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**ANT 3**  
**Band 2, BW 10MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM









**Band 2, BW 10MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 10MHz, Single carrier, 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (219) / (1312)  
 Pages

**ANT 4**  
**Band 2, BW 10MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 10MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 10MHz, Single carrier, 4TX, Top**


QPSK




16QAM



64QAM




256QAM






**ANT 1**  
**Band 2, BW 15MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 15MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (224) / (1312)  
 Pages

**Band 2, BW 15MHz, Single carrier, 4TX, Top**


QPSK




16QAM



64QAM



256QAM









**ANT 2**  
**Band 2, BW 15MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 15MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 15MHz, Single carrier, 4TX, Top**


QPSK




16QAM



64QAM




256QAM






**ANT 3**  
**Band 2, BW 15MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 15MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 15MHz, Single carrier, 4TX Top**


QPSK




16QAM



64QAM




256QAM






**ANT 4**  
**Band 2, BW 15MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 15MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM



256QAM









**Band 2, BW 15MHz, Single carrier, 4TX, Top**


QPSK




16QAM



64QAM




256QAM






**ANT 1**  
**Band 2, BW 20MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 20MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 20MHz, Single carrier, 4TX, Top**


QPSK




16QAM



64QAM




256QAM






**ANT 2**  
**Band 2, BW 20MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 20MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (239) / (1312)  
 Pages

**Band 2, BW 20MHz, Single carrier, 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (240) / (1312)  
 Pages

**ANT 3**  
**Band 2, BW 20MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM









**Band 2, BW 20MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 20MHz, Single carrier, 4TX, Top**


QPSK




16QAM



64QAM




256QAM






**ANT 4**  
**Band 2, BW 20MHz, Single carrier, 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 20MHz, Single carrier, 4TX, Middle**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 20MHz, Single carrier, 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03328  
 Page (246) / (1312)  
 Pages

**ANT 1**

**Band 2, BW 5MHz + BW 5MHz, Multi carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (247) / (1312)  
 Pages

**Band 2, BW 5MHz + BW 5MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (248) / (1312)  
 Pages

**ANT 2**

**Band 2, BW 5MHz + BW 5MHz, Multi carrier(Contiguous), 4TX, Bottom**


QPSK

16QAM



64QAM

256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (249) / (1312)  
 Pages

**Band 2, BW 5MHz + BW 5MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (250) / (1312)  
 Pages

**ANT 3**

**Band 2, BW 5MHz + BW 5MHz, Multi carrier(Contiguous), 4TX, Bottom**

QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (251) / (1312)  
 Pages

**Band 2, BW 5MHz + BW 5MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03328  
 Page (252) / (1312)  
 Pages

**ANT 4**

**Band 2, BW 5MHz + BW 5MHz, Multi carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (253) / (1312)  
 Pages

**Band 2, BW 5MHz + BW 5MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**ANT 1**

**Band 2, BW 5MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Bottom**

QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (255) / (1312)  
 Pages

**Band 2, BW 5MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03328  
 Page (256) / (1312)  
 Pages

**ANT 2**

**Band 2, BW 5MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (257) / (1312)  
 Pages

**Band 2, BW 5MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 3**

**Band 2, BW 5MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (259) / (1312)  
 Pages

**Band 2, BW 5MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (260) / (1312)  
 Pages

**ANT 4**

**Band 2, BW 5MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (261) / (1312)  
 Pages

**Band 2, BW 5MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (262) / (1312)  
 Pages


**ANT 1**

**Band 2, BW 5MHz + BW 15MHz, Multi carrier(Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM




256QAM






**Band 2, BW 5MHz + BW 15MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (264) / (1312)  
 Pages

**ANT 2**

**Band 2, BW 5MHz + BW 15MHz, Multi carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM









**Band 2, BW 5MHz + BW 15MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 3**

**Band 2, BW 5MHz + BW 15MHz, Multi carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (267) / (1312)  
 Pages

**Band 2, BW 5MHz + BW 15MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 4**

**Band 2, BW 5MHz + BW 15MHz, Multi carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (269) / (1312)  
 Pages

**Band 2, BW 5MHz + BW 15MHz, Multi carrier(Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM






**ANT 1**

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (271) / (1312)  
 Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03328  
 Page (272) / (1312)  
 Pages

**ANT 2**

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM









**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (273) / (1312)  
 Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Top**



QPSK

16QAM



64QAM

256QAM







**ANT 3**

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (275) / (1312)  
 Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM







**ANT 4**

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (277) / (1312)  
 Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03328  
 Page (278) / (1312)  
 Pages

**ANT 1**

**Band 2, BW 15MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (279) / (1312)  
 Pages

**Band 2, BW 15MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Top**

QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (280) / (1312)  
 Pages


**ANT 2**

**Band 2, BW 15MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (281) / (1312)  
 Pages

**Band 2, BW 15MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Top**

QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03328  
 Page (282) / (1312)  
 Pages

**ANT 3**

**Band 2, BW 15MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (283) / (1312)  
 Pages

**Band 2, BW 15MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Top**

QPSK



16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03328  
 Page (284) / (1312)  
 Pages

**ANT 4**

**Band 2, BW 15MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (285) / (1312)  
 Pages

**Band 2, BW 15MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Top**

QPSK




16QAM



64QAM



256QAM






**ANT 1**

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (287) / (1312)  
 Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03328  
 Page (288) / (1312)  
 Pages

**ANT 2**

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (289) / (1312)  
 Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (290) / (1312)  
 Pages

**ANT 3**

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (291) / (1312)  
 Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2018-03328  
 Page (292) / (1312)  
 Pages

**ANT 4**

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**



QPSK

16QAM



64QAM

256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (293) / (1312)  
 Pages

**Band 2, BW 10MHz + BW 10MHz, Multi carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**ANT 1**

**Band 2, BW 10MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (295) / (1312)  
 Pages

**Band 2, BW 10MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (296) / (1312)  
 Pages

**ANT 2**

**Band 2, BW 10MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501


Report No.:  
 CTK-2018-03328  
 Page (297) / (1312)  
 Pages

**Band 2, BW 10MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (298) / (1312)  
 Pages

**ANT 3**

**Band 2, BW 10MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (299) / (1312)  
 Pages

**Band 2, BW 10MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Top**


QPSK




16QAM



64QAM



256QAM






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2018-03328  
 Page (300) / (1312)  
 Pages

**ANT 4**

**Band 2, BW 10MHz + BW 5MHz, Multi carrier(Non-Contiguous), 4TX, Bottom**


QPSK



16QAM



64QAM



256QAM

