




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (82) / (192)
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (83) / (192)
 Pages

ANT 2
[QPSK]


9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 860 MHz



860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (84) / (192)
 Pages

[16QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2021-00289
 Page (85) / (192)
 Pages

[64QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 860 MHz




860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (86) / (192)
 Pages

[256QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 860 MHz



860 MHz - 868 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (87) / (192)
 Pages

**BW 10MHz+5MHz, Multi 2 carrier(Contiguous), 2Tx, Middle
 ANT 1
 [QPSK]**





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (88) / (192)
 Pages

[16QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2021-00289
 Page (89) / (192)
 Pages

[64QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (90) / (192)
 Pages

[256QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (91) / (192)
 Pages

ANT 2
[QPSK]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (92) / (192)
 Pages

[16QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2021-00289
 Page (93) / (192)
 Pages

[64QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2021-00289
 Page (94) / (192)
 Pages

[256QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz



894 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (95) / (192)
 Pages

**BW 10MHz+5MHz, Multi 2 carrier(Contiguous), 2Tx, Top
 ANT 1
 [QPSK]**

9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 869 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (96) / (192)
 Pages

[16QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 869 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2021-00289
 Page (97) / (192)
 Pages

[64QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 869 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (98) / (192)
 Pages

[256QAM]


9 kHz - 150 kHz




150 kHz - 30 MHz



30 MHz - 869 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (99) / (192)
 Pages

ANT 2
[QPSK]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 869 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (100) / (192)
 Pages

[16QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 869 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2021-00289
 Page (101) / (192)
 Pages

[64QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 869 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (102) / (192)
 Pages

[256QAM]


9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 869 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (103) / (192)
 Pages

**BW 10MHz+5MHz, Multi 2 carrier(Non-Contiguous), 2Tx, Bottom/Top
 ANT 1
 [QPSK]**

9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz



895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (104) / (192)
 Pages

[16QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz



895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2021-00289
 Page (105) / (192)
 Pages

[64QAM]

9 kHz - 150 kHz



150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2021-00289
 Page (106) / (192)
 Pages

[256QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz



895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (107) / (192)
 Pages

ANT 2
[QPSK]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz




895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-00289
 Page (108) / (192)
 Pages

[16QAM]

9 kHz - 150 kHz




150 kHz - 30 MHz




30 MHz - 860 MHz




860 MHz - 868 MHz



895 MHz - 905 MHz



905 MHz - 1 GHz



1 GHz - 12.75 GHz

