

KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0123-A


Page (69) of (116)



10M BW / QPSK / Low ch. / 1RB



10M BW / QPSK / High ch. / 1RB




10M BW / QPSK / Low ch. / 1RB




10M BW / QPSK / High ch. / 1RB




10M BW / 16QAM / Low ch. / 1RB




10M BW / 16QAM / High ch. / 1RB



10M BW / 16QAM / Low ch. / 1RB



10M BW / 16QAM / High ch. / 1RB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0123-A


Page (70) of (116)



10M BW / QPSK / Lower extended / 1RB



10M BW / QPSK / Upper extended / 1RB




10M BW / QPSK / Lower extended / FRB




10M BW / QPSK / Upper extended / FRB




10M BW / 16QAM / Lower extended / 1RB




10M BW / 16QAM / Upper extended / 1RB



10M BW / 16QAM / Lower extended / FRB



10M BW / 16QAM / Upper extended / FRB



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR19-SRF0123-A

Page (71) of (116)




Test mode: LTE Band 26


1.4M BW / QPSK / Low ch. / 1RB




1.4M BW / QPSK / High ch. / 1RB




1.4M BW / QPSK / Low ch. / FRB




1.4M BW / QPSK / High ch. / FRB




1.4M BW / 16QAM / Low ch. / 1RB




1.4M BW / 16QAM / High ch. / 1RB



1.4M BW / 16QAM / Low ch. / FRB



1.4M BW / 16QAM / High ch. / FRB



This test report shall not be reproduced, except in full, without the written approval

KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0123-A


Page (72) of (116)



1.4M BW / QPSK / Lower extended / 1RB



1.4M BW / QPSK / Upper extended / 1RB




1.4M BW / QPSK / Lower extended / FRB




1.4M BW / QPSK / Upper extended / FRB




1.4M BW / 16QAM / Lower extended / 1RB




1.4M BW / 16QAM / Upper extended / 1RB



1.4M BW / 16QAM / Lower extended / FRB



1.4M BW / 16QAM / Upper extended / FRB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0123-A


Page (73) of (116)




3M BW / QPSK / Low ch. / 1RB



3M BW / QPSK / High ch. / 1RB




3M BW / QPSK / Low ch. / FRB




3M BW / QPSK / High ch. / FRB




3M BW / 16QAM / Low ch. / 1RB




3M BW / 16QAM / High ch. / 1RB



3M BW / 16QAM / Low ch. / FRB



3M BW / 16QAM / High ch. / FRB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0123-A


Page (74) of (116)



3M BW / QPSK / Lower extended / 1RB



3M BW / QPSK / Upper extended / 1RB



3M BW / QPSK / Lower extended / FRB




3M BW / QPSK / Upper extended / FRB




3M BW / 16QAM / Lower extended / 1RB



3M BW / 16QAM / Upper extended / 1RB



3M BW / QPSK / Lower extended / FRB



3M BW / QPSK / Upper extended / FRB

