

KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0123-A


Page (75) of (116)



5M BW / QPSK / Low ch. / 1RB



5M BW / QPSK / High ch. / 1RB



5M BW / QPSK / Low ch. / FRB




5M BW / QPSK / High ch. / FRB




5M BW / 16QAM / Low ch. / 1RB




5M BW / 16QAM / High ch. / 1RB



5M BW / 16QAM / Low ch. / FRB



5M BW / 16QAM / High ch. / FRB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0123-A


Page (76) of (116)



5M BW / QPSK / Lower extended / 1RB



5M BW / QPSK / Upper extended / 1RB




5M BW / QPSK / Lower extended / FRB




5M BW / QPSK / Upper extended / FRB




5M BW / 16QAM / Lower extended / 1RB




5M BW / 16QAM / Upper extended / 1RB



5M BW / 16QAM / Lower extended / FRB



5M BW / 16QAM / Upper extended / FRB



This test report shall not be reproduced, except in full, without the written approval

KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0123-A


Page (77) of (116)




10M BW / QPSK / Low ch. / 1RB



10M BW / QPSK / High ch. / 1RB




10M BW / QPSK / Low ch. / FRB




10M BW / QPSK / High ch. / FRB




10M BW / 16QAM / Low ch. / 1RB




10M BW / 16QAM / High ch. / 1RB



10M BW / 16QAM / Low ch. / FRB



10M BW / 16QAM / High ch. / FRB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0123-A


Page (78) of (116)



10M BW / QPSK / Lower extended / 1RB



10M BW / QPSK / Upper extended / 1RB




10M BW / QPSK / Lower extended / FRB




10M BW / QPSK / Upper extended / FRB




10M BW / 16QAM / Lower extended / 1RB




10M BW / 16QAM / Upper extended / 1RB



10M BW / 16QAM / Lower extended / FRB



10M BW / 16QAM / Upper extended / FRB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0123-A


Page (79) of (116)



15M BW / QPSK / Low ch. / 1RB



15M BW / QPSK / High ch. / 1RB




15M BW / QPSK / Low ch. / FRB




15M BW / QPSK / High ch. / FRB




15M BW / 16QAM / Low ch. / 1RB




15M BW / 16QAM / High ch. / 1RB



15M BW / 16QAM / Low ch. / FRB



15M BW / 16QAM / High ch. / FRB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0123-A


Page (80) of (116)




15M BW / QPSK / Lower extended / 1RB



15M BW / QPSK / Upper extended / 1RB



15M BW / QPSK / Lower extended / FRB




15M BW / QPSK / Upper extended / FRB




15M BW / 16QAM / Lower extended / 1RB



15M BW / 16QAM / Upper extended / 1RB



15M BW / 16QAM / Lower extended / FRB



15M BW / 16QAM / Upper extended / FRB

