



Appendix C. Test Photo

Right Cheek



Right Tilt




KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR19-SPF0005-B
Page (179) of (194)

KCTL

Left Cheek



Left Tilt



Front (0 mm)



Front (10 mm)




Front (15 mm)




Rear (0 mm)



Rear (10 mm)




Rear-ear (10 mm)




Rear (12 mm)




Rear (15 mm)



Rear-ear (15 mm)



Left (0 mm)




KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR19-SPF0005-B
Page (185) of (194)



Left (10 mm)



Right (0 mm)



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR19-SPF0005-B
Page (186) of (194)




Right (10 mm)




Top (10 mm)



Bottom (0 mm)



Bottom (8 mm)




KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SPF0005-B
Page (188) of (194)

KCTL

Bottom (10 mm)



KCTL


KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR19-SPF0005-B
Page (189) of (194)



System Check 750 MHz



System Check 900 MHz




KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR19-SPF0005-B
Page (190) of (194)



System Check 1 750 MHz



System Check 1 900 MHz




KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SPF0005-B
Page (191) of (194)

KCTL

System Check 2 450 MHz



KCTL

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR19-SPF0005-B
Page (192) of (194)



Liquid Depth HSL 900



Liquid Depth HSL 1900




KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR19-SPF0005-B
Page (193) of (194)



Liquid Depth HSL 2450



Liquid Depth MSL 900



KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SPF0005-B
Page (194) of (194)

KCTL

Liquid Depth MSL 1900



Liquid Depth MSL 2450



End of test report