


# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (151) of (220)




## 3M BW QPSK Low ch. 1RB




## 3M BW QPSK High ch. 1RB




## 3M BW QPSK Low ch. FRB




## 3M BW QPSK High ch. FRB




## 3M BW 16QAM Low ch. 1RB




## 3M BW 16QAM High ch. 1RB



## 3M BW 16QAM Low ch. FRB



## 3M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (152) of (220)




## 3M BW QPSK Lower extended 1RB



## 3M BW QPSK Upper extended 1RB



## 3M BW QPSK Lower extended FRB



## 3M BW QPSK Upper extended FRB




## 3M BW 16QAM Lower extended 1RB



## 3M BW 16QAM Upper extended 1RB



## 3M BW 16QAM Lower extended FRB



## 3M BW 16QAM Upper extended FRB



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SRF0060  
Page (153) of (220)



## Test mode: LTE Band 12/17


### 5M BW QPSK Low ch. 1RB



### 5M BW QPSK High ch. 1RB




### 5M BW QPSK Low ch. FRB




### 5M BW QPSK High ch. FRB




### 5M BW 16QAM Low ch. 1RB



### 5M BW 16QAM High ch. 1RB



### 5M BW 16QAM Low ch. FRB



### 5M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (154) of (220)




## 5M BW QPSK Lower extended 1RB




## 5M BW QPSK Upper extended 1RB




## 5M BW QPSK Lower extended FRB




## 5M BW QPSK Upper extended FRB




## 5M BW 16QAM Lower extended 1RB



## 5M BW 16QAM Upper extended 1RB



## 5M BW 16QAM Lower extended FRB



## 5M BW 16QAM Upper extended FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (155) of (220)




## 10M BW QPSK Low ch. 1RB




## 10M BW QPSK High ch. 1RB




## 10M BW QPSK Low ch. FRB




## 10M BW QPSK High ch. FRB



## 10M BW 16QAM Low ch. 1RB




## 10M BW 16QAM High ch. 1RB



## 10M BW 16QAM Low ch. FRB



## 10M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (156) of (220)




## 10M BW QPSK Lower extended 1RB




## 10M BW QPSK Upper extended 1RB




## 10M BW QPSK Lower extended FRB




## 10M BW QPSK Upper extended FRB




## 10M BW 16QAM Lower extended 1RB




## 10M BW 16QAM Upper extended 1RB



## 10M BW 16QAM Lower extended FRB



## 10M BW 16QAM Upper extended FRB



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SRF0060  
Page (157) of (220)




## Test mode: LTE Band 26


### 1.4M BW QPSK Low ch. 1RB



### 1.4M BW QPSK High ch. 1RB




### 1.4M BW QPSK Low ch. FRB




### 1.4M BW QPSK High ch. FRB




### 1.4M BW 16QAM Low ch. 1RB



### 1.4M BW 16QAM High ch. 1RB



### 1.4M BW 16QAM Low ch. FRB



### 1.4M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (158) of (220)




## 1.4M BW QPSK Lower extended 1RB




## 1.4M BW QPSK Upper extended 1RB




## 1.4M BW QPSK Lower extended FRB



## 1.4M BW QPSK Upper extended FRB



## 1.4M BW 16QAM Lower extended 1RB



## 1.4M BW 16QAM Upper extended 1RB



## 1.4M BW 16QAM Lower extended FRB



## 1.4M BW 16QAM Upper extended FRB






# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (159) of (220)



## 3M BW QPSK Low ch. 1RB




## 3M BW QPSK High ch. 1RB




## 3M BW QPSK Low ch. FRB




## 3M BW QPSK High ch. FRB




## 3M BW 16QAM Low ch. 1RB




## 3M BW 16QAM High ch. 1RB



## 3M BW 16QAM Low ch. FRB



## 3M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (160) of (220)



## 3M BW QPSK Lower extended 1RB



## 3M BW QPSK Upper extended 1RB




## 3M BW QPSK Lower extended FRB




## 3M BW QPSK Upper extended FRB



## 3M BW 16QAM Lower extended 1RB



## 3M BW 16QAM Upper extended 1RB



## 3M BW 16QAM Lower extended FRB



## 3M BW 16QAM Upper extended FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (161) of (220)



## 5M BW QPSK Low ch. 1RB




## 5M BW QPSK High ch. 1RB




## 5M BW QPSK Low ch. FRB




## 5M BW QPSK High ch. FRB




## 5M BW 16QAM Low ch. 1RB



## 5M BW 16QAM High ch. 1RB



## 5M BW 16QAM Low ch. FRB



## 5M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (162) of (220)




## 5M BW QPSK Lower extended 1RB



## 5M BW QPSK Upper extended 1RB




## 5M BW QPSK Lower extended FRB



## 5M BW QPSK Upper extended FRB




## 5M BW 16QAM Lower extended 1RB



## 5M BW 16QAM Upper extended 1RB



## 5M BW 16QAM Lower extended FRB



## 5M BW 16QAM Upper extended FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (163) of (220)




## 10M BW QPSK Low ch. 1RB




## 10M BW QPSK High ch. 1RB




## 10M BW QPSK Low ch. FRB




## 10M BW QPSK High ch. FRB




## 10M BW 16QAM Low ch. 1RB



## 10M BW 16QAM High ch. 1RB



## 10M BW 16QAM Low ch. FRB



## 10M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (164) of (220)




## 10M BW QPSK Lower extended 1RB




## 10M BW QPSK Upper extended 1RB




## 10M BW QPSK Lower extended FRB




## 10M BW QPSK Upper extended FRB




## 10M BW 16QAM Lower extended 1RB



## 10M BW 16QAM Upper extended 1RB



## 10M BW 16QAM Lower extended FRB



## 10M BW 16QAM Upper extended FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (165) of (220)




## 15M BW QPSK Low ch. 1RB




## 15M BW QPSK High ch. 1RB




## 15M BW QPSK Low ch. FRB




## 15M BW QPSK High ch. FRB




## 15M BW 16QAM Low ch. 1RB




## 15M BW 16QAM High ch. 1RB



## 15M BW 16QAM Low ch. FRB



## 15M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (166) of (220)




## 15M BW QPSK Lower extended 1RB




## 15M BW QPSK Upper extended 1RB




## 15M BW QPSK Lower extended FRB




## 15M BW QPSK Upper extended FRB




## 15M BW 16QAM Lower extended 1RB



## 15M BW 16QAM Upper extended 1RB



## 15M BW 16QAM Lower extended FRB



## 15M BW 16QAM Upper extended FRB



Test mode: LTE Band 41




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (167) of (220)




## 5M BW QPSK Low ch. 1RB




## 5M BW QPSK High ch. 1RB




## 5M BW QPSK Low ch. FRB



## 5M BW QPSK High ch. FRB



## 5M BW 16QAM Low ch. 1RB




## 5M BW 16QAM High ch. 1RB



## 5M BW 16QAM Low ch. FRB



## 5M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (168) of (220)




## 10M BW QPSK Low ch. 1RB




## 10M BW QPSK High ch. 1RB




## 10M BW QPSK Low ch. FRB




## 10M BW QPSK High ch. FRB




## 10M BW 16QAM Low ch. 1RB




## 10M BW 16QAM High ch. 1RB



## 10M BW 16QAM Low ch. FRB



## 10M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (169) of (220)




## 15M BW QPSK Low ch. 1RB




## 15M BW QPSK High ch. 1RB




## 15M BW / QPSK / Low ch. / FRB




## 15M BW / QPSK / High ch. / FRB




## 15M BW 16QAM Low ch. 1RB



## 15M BW 16QAM High ch. 1RB



## 15M BW 16QAM Low ch. FRB



## 15M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (170) of (220)




## 20M BW QPSK Low ch. 1RB




## 20M BW QPSK High ch. 1RB




## 20M BW QPSK Low ch. FRB




## 20M BW QPSK High ch. FRB




## 20M BW 16QAM Low ch. 1RB




## 20M BW 16QAM High ch. 1RB



## 20M BW 16QAM Low ch. FRB



## 20M BW 16QAM High ch. FRB



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR21-SRF0060  
Page (171) of (220)




## Test mode: LTE Band 66/4


### 1.4M BW QPSK Low ch. 1RB




### 1.4M BW QPSK High ch. 1RB




### 1.4M BW QPSK Low ch. FRB




### 1.4M BW QPSK High ch. FRB




### 1.4M BW 16QAM Low ch. 1RB



### 1.4M BW 16QAM High ch. 1RB



### 1.4M BW 16QAM Low ch. FRB



### 1.4M BW 16QAM High ch. FRB




### 3M BW QPSK Low ch. 1RB

### 3M BW QPSK High ch. 1RB


# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (172) of (220)




**3M BW QPSK Low ch. FRB**




**3M BW QPSK High ch. FRB**




**3M BW 16QAM Low ch. 1RB**





**3M BW 16QAM High ch. 1RB**



**3M BW 16QAM Low ch. FRB**



**3M BW 16QAM High ch. FRB**




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (173) of (220)




## 5M BW QPSK Low ch. 1RB




## 5M BW QPSK High ch. 1RB




## 5M BW QPSK Low ch. FRB




## 5M BW QPSK High ch. FRB




## 5M BW 16QAM Low ch. 1RB



## 5M BW 16QAM High ch. 1RB



## 5M BW 16QAM Low ch. FRB



## 5M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (174) of (220)




## 10M BW QPSK Low ch. 1RB




## 10M BW QPSK High ch. 1RB




## 10M BW QPSK Low ch. FRB




## 10M BW QPSK High ch. FRB




## 10M BW 16QAM Low ch. 1RB




## 10M BW 16QAM High ch. 1RB



## 10M BW 16QAM Low ch. FRB



## 10M BW 16QAM High ch. FRB






# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (175) of (220)




## 15M BW QPSK Low ch. 1RB



## 15M BW QPSK High ch. 1RB




## 15M BW QPSK Low ch. FRB




## 15M BW QPSK High ch. FRB




## 15M BW 16QAM Low ch. 1RB



## 15M BW 16QAM High ch. 1RB



## 15M BW 16QAM Low ch. FRB



## 15M BW 16QAM High ch. FRB




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR21-SRF0060  
Page (176) of (220)




## 20M BW QPSK Low ch. 1RB




## 20M BW QPSK High ch. 1RB




## 20M BW QPSK Low ch. FRB




## 20M BW QPSK High ch. FRB




## 20M BW 16QAM Low ch. 1RB



## 20M BW 16QAM High ch. 1RB



## 20M BW 16QAM Low ch. FRB



## 20M BW 16QAM High ch. FRB

