

KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr


Report No.:
KR19-SRF0167-C

Page (53) of (89)


KCTL

Test mode: LTE Band 26 (Part 22H)


1.4M BW / QPSK / Low ch. / 1RB




1.4M BW / QPSK / High ch. / 1RB




1.4M BW / QPSK / Low ch. / FRB




1.4M BW / QPSK / High ch. / FRB




1.4M BW / 16QAM / Low ch. / 1RB




1.4M BW / 16QAM / High ch. / 1RB



1.4M BW / 16QAM / Low ch. / FRB



1.4M BW / 16QAM / High ch. / FRB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0167-C


Page (54) of (89)




1.4M BW / QPSK / Lower extended / 1RB



1.4M BW / QPSK / Upper extended / 1RB




1.4M BW / QPSK / Lower extended / FRB




1.4M BW / QPSK / Upper extended / FRB




1.4M BW / 16QAM / Lower extended / 1RB




1.4M BW / 16QAM / Upper extended / 1RB



1.4M BW / 16QAM / Lower extended / FRB



1.4M BW / 16QAM / Upper extended / FRB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0167-C


Page (55) of (89)




3M BW / QPSK / Low ch. / 1RB




3M BW / QPSK / High ch. / 1RB




3M BW / QPSK / Low ch. / FRB




3M BW / QPSK / High ch. / FRB




3M BW / 16QAM / Low ch. / 1RB




3M BW / 16QAM / High ch. / 1RB



3M BW / 16QAM / Low ch. / FRB



3M BW / 16QAM / High ch. / FRB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0167-C


Page (56) of (89)




3M BW / QPSK / Lower extended / 1RB



3M BW / QPSK / Upper extended / 1RB




3M BW / QPSK / Lower extended / FRB




3M BW / QPSK / Upper extended / FRB




3M BW / 16QAM / Lower extended / 1RB




3M BW / 16QAM / Upper extended / 1RB



3M BW / 16QAM / Lower extended / FRB



3M BW / 16QAM / Upper extended / FRB



KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,
Suwon-si, Gyeonggi-do, 16677, Korea
TEL: 82-31-285-0894 FAX: 82-505-299-8311
www.kctl.co.kr

Report No.:
KR19-SRF0167-C


Page (57) of (89)




5M BW / QPSK / Low ch. / 1RB




5M BW / QPSK / High ch. / 1RB




5M BW / QPSK / Low ch. / FRB




5M BW / QPSK / High ch. / FRB




5M BW / 16QAM / Low ch. / 1RB



5M BW / 16QAM / High ch. / 1RB



5M BW / 16QAM / Low ch. / FRB



5M BW / 16QAM / High ch. / FRB

