

Device is not operating with TX
on LTE B7/B38 in US Market

Model Name : SM-G390Y

2017.3.10

1. UE does not operate with LTE B7/B38 in United States live network if there's no LTE B7/B38 service.
2. The right flow chart shows how UE operate on B7/B38.
3. UE will check MCC from SIB(System Information Block) message which is broadcasted by network.
4. There's no any TX operation on B7/B38 because UE just read this information from the broadcasting message.

