


# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (125) of (278)




## 20M BW QPSK Low ch.




## 20M BW 16QAM Low ch.




## 20M BW QPSK Mid ch.




## 20M BW 16QAM Mid ch.



## 20M BW QPSK High ch.



## 20M BW 16QAM High ch.



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR22-SRF0086-C  
Page (126) of (278)




## Test mode: LTE Band 5


### 1.4M BW QPSK Low ch.




### 1.4M BW 16QAM Low ch.




### 1.4M BW QPSK Mid ch.




### 1.4M BW 16QAM Mid ch.



### 1.4M BW QPSK High ch.



### 1.4M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (127) of (278)




## 3M BW QPSK Low ch.




## 3M BW 16QAM Low ch.




## 3M BW QPSK Mid ch.




## 3M BW 16QAM Mid ch.



## 3M BW QPSK High ch.



## 3M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (128) of (278)




## 5M BW QPSK Low ch.




## 5M BW 16QAM Low ch.




## 5M BW QPSK Mid ch.




## 5M BW 16QAM Mid ch.



## 5M BW QPSK High ch.



## 5M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (129) of (278)




## 10M BW QPSK Low ch.




## 10M BW 16QAM Low ch.




## 10M BW QPSK Mid ch.




## 10M BW 16QAM Mid ch.



## 10M BW QPSK High ch.



## 10M BW 16QAM High ch.



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR22-SRF0086-C  
Page (130) of (278)




## Test mode: LTE Band 12


### 1.4M BW QPSK Low ch.




### 1.4M BW 16QAM Low ch.




### 1.4M BW QPSK Mid ch.




### 1.4M BW 16QAM Mid ch.



### 1.4M BW QPSK High ch.



### 1.4M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (131) of (278)




## 3M BW QPSK Low ch.




## 3M BW 16QAM Low ch.




## 3M BW QPSK Mid ch.




## 3M BW 16QAM Mid ch.



## 3M BW QPSK High ch.



## 3M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (132) of (278)




## 5M BW QPSK Low ch.




## 5M BW 16QAM Low ch.




## 5M BW QPSK Mid ch.




## 5M BW 16QAM Mid ch.



## 5M BW QPSK High ch.



## 5M BW 16QAM High ch.





# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR22-SRF0086-C  
Page (133) of (278)




KCTL


## 10M BW QPSK Low ch.




## 10M BW 16QAM Low ch.




## 10M BW QPSK Mid ch.




## 10M BW 16QAM Mid ch.



## 10M BW QPSK High ch.



## 10M BW 16QAM High ch.



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR22-SRF0086-C  
Page (134) of (278)




## Test mode: LTE Band 13


### 5 M BW QPSK Low ch.




### 5 M BW 16QAM Low ch.




### 5 M BW QPSK Mid ch.




### 5 M BW 16QAM Mid ch.



### 5 M BW QPSK High ch.



### 5 M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (135) of (278)



## 10M BW QPSK Low ch.



## 10M BW 16QAM Low ch.



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR22-SRF0086-C  
Page (136) of (278)




## Test mode: LTE Band 25


### 1.4M BW QPSK Low ch.




### 1.4M BW 16QAM Low ch.




### 1.4M BW QPSK Mid ch.




### 1.4M BW 16QAM Mid ch.



### 1.4M BW QPSK High ch.



### 1.4M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (137) of (278)




## 3M BW QPSK Low ch.




## 3M BW 16QAM Low ch.




## 3M BW QPSK Mid ch.




## 3M BW 16QAM Mid ch.



## 3M BW QPSK High ch.



## 3M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (138) of (278)




## 5M BW QPSK Low ch.




## 5M BW 16QAM Low ch.




## 5M BW QPSK Mid ch.




## 5M BW 16QAM Mid ch.



## 5M BW QPSK High ch.



## 5M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (139) of (278)




## 10M BW QPSK Low ch.




## 10M BW 16QAM Low ch.




## 10M BW QPSK Mid ch.




## 10M BW 16QAM Mid ch.



## 10M BW QPSK High ch.



## 10M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (140) of (278)




## 15M BW QPSK Low ch.




## 15M BW 16QAM Low ch.




## 15M BW QPSK Mid ch.




## 15M BW 16QAM Mid ch.



## 15M BW QPSK High ch.



## 15M BW 16QAM High ch.






# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (141) of (278)




## 20M BW QPSK Low ch.




## 20M BW 16QAM Low ch.




## 20M BW QPSK Mid ch.




## 20M BW 16QAM Mid ch.



## 20M BW QPSK High ch.



## 20M BW 16QAM High ch.



# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (142) of (278)




KCTL

## Test mode: LTE Band 26


### 1.4M BW QPSK Low ch.




### 1.4M BW 16QAM Low ch.




### 1.4M BW QPSK Mid ch.




### 1.4M BW 16QAM Mid ch.



### 1.4M BW QPSK High ch.



### 1.4M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (143) of (278)




## 3M BW QPSK Low ch.




## 3M BW 16QAM Low ch.




## 3M BW QPSK Mid ch.




## 3M BW 16QAM Mid ch.



## 3M BW QPSK High ch.



## 3M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (144) of (278)




## 5M BW QPSK Low ch.




## 5M BW 16QAM Low ch.




## 5M BW QPSK Mid ch.




## 5M BW 16QAM Mid ch.



## 5M BW QPSK High ch.



## 5M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (145) of (278)




## 10M BW QPSK Low ch.




## 10M BW 16QAM Low ch.




## 10M BW QPSK Mid ch.




## 10M BW 16QAM Mid ch.



## 10M BW QPSK High ch.



## 10M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (146) of (278)




## 15M BW QPSK Low ch.




## 15M BW 16QAM Low ch.




## 15M BW QPSK Mid ch.




## 15M BW 16QAM Mid ch.



## 15M BW QPSK High ch.



## 15M BW 16QAM High ch.



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR22-SRF0086-C  
Page (147) of (278)




## Test mode: LTE Band 66/4


### 1.4M BW QPSK Low ch.




### 1.4M BW 16QAM Low ch.




### 1.4M BW QPSK Mid ch.




### 1.4M BW 16QAM Mid ch.



### 1.4M BW QPSK High ch.



### 1.4M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (148) of (278)




## 3M BW QPSK Low ch.




## 3M BW 16QAM Low ch.




## 3M BW QPSK Mid ch.




## 3M BW 16QAM Mid ch.



## 3M BW QPSK High ch.



## 3M BW 16QAM High ch.






# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (149) of (278)




## 5M BW QPSK Low ch.




## 5M BW 16QAM Low ch.




## 5M BW QPSK Mid ch.




## 5M BW 16QAM Mid ch.



## 5M BW QPSK High ch.



## 5M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (150) of (278)




## 10M BW QPSK Low ch.




## 10M BW 16QAM Low ch.




## 10M BW QPSK Mid ch.




## 10M BW 16QAM Mid ch.



## 10M BW QPSK High ch.



## 10M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (151) of (278)




## 15M BW QPSK Low ch.




## 15M BW 16QAM Low ch.




## 15M BW QPSK Mid ch.




## 15M BW 16QAM Mid ch.



## 15M BW QPSK High ch.



## 15M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (152) of (278)




## 20M BW QPSK Low ch.




## 20M BW 16QAM Low ch.




## 20M BW QPSK Mid ch.




## 20M BW 16QAM Mid ch.



## 20M BW QPSK High ch.



## 20M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR22-SRF0086-C  
Page (153) of (278)



## Test mode: LTE Band 71




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (154) of (278)




## 10M BW QPSK Low ch.




## 10M BW 16QAM Low ch.




## 10M BW QPSK Mid ch.




## 10M BW 16QAM Mid ch.



## 10M BW QPSK High ch.



## 10M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (155) of (278)




## 15M BW QPSK Low ch.




## 15M BW 16QAM Low ch.




## 15M BW QPSK Mid ch.




## 15M BW 16QAM Mid ch.



## 15M BW QPSK High ch.



## 15M BW 16QAM High ch.




# KCTL Inc.

65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)


Report No.:  
KR22-SRF0086-C  
Page (156) of (278)




## 20M BW QPSK Low ch.




## 20M BW 16QAM Low ch.




## 20M BW QPSK Mid ch.



## 20M BW 16QAM Mid ch.



## 20M BW QPSK High ch.



## 20M BW 16QAM High ch.

